

Flight Evaluation of the Communications Earplug in the OH-58D Helicopter

Part 2. Questionnaire Data

By

Barbara A. Murphy and Ben T. Mozo

Aircrew Protection Division

October 1999

DTIC QUALITY INSPECTED 4

19991209 059

Approved for public release, distribution unlimited.

U.S. Army Aeromedical Research Laboratory Fort Rucker, Alabama 36362-0577

Notice

Qualified requesters

Qualified requesters may obtain copies from the Defense Technical Information Center (DTIC), Cameron Station, Alexandria, Virginia 22314. Orders will be expedited if placed through the librarian or other person designated to request documents from DTIC.

Change of address

Organizations receiving reports from the U.S. Army Aeromedical Research Laboratory on automatic mailing lists should confirm correct address when corresponding about laboratory reports.

Disposition

Destroy this document when it is no longer needed. Do not return it to the originator.

Disclaimer

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy, or decision, unless so designated by other official documentation. Citation of trade names in this report does not constitute an official Department of the Army endorsement or approval of the use of such commercial items.

Human use

Human subjects participated in these studies after giving their free and informed voluntary consent. Investigators adhered to AR 70-25 and USAMRMC Reg 70-25 on Use of Volunteers in Research.

| REPOR | RT DO | CUMENTATIO | ON PAGE | | | Form Ap OMB No | proved b. 0704-0188 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------------------|
| 1a. REPORT SECURITY CLASSIFICATION Unclassified | | | 1b. RESTRICTIV | E MARKINGS | | | |
| 2a. SECURITY CLASSIFICATION AUTHORITY | , | | 3. DISTRIBUTION Approved | N/AVAILABILITY OF REPO for public rel | RT ease, | dist | cribution |
| 2b. DECLASSIFICATION / DOWNGRADING SC | CHEDULE | | unlimited | i. | | | |
| 4. PERFORMING ORGANIZATION REPORT NO USAARL Report No. 2000-05 | | | 5. MONITORING | ORGANIZATION REPORT | NUMBER | R(S) | |
| 6a. NAME OF PERFORMING ORGANIZATION U.S. Army Aeromedical Research Laboratory | | 6b. OFFICE SYMBOL (If applicable) MCMR-UAD | U.S. Army | ONITORING ORGANIZATIO 7 Medical Resea Command (USAMR | rch a | ınd | |
| 6c. ADDRESS (City, State, and ZIP Code) P.O. Box 620577 Fort Rucker, AL 36362-0 | 577 | | 504 Scott | City, State, and ZIP Code) t Street, rick, MD 21702- | 5012 | | |
| 8a. NAME OF FUNDING/SPONSORING ORGANIZATION US Army Medical Rsch Acq | Act | 8b. OFFICE SYMBOL (If applicable) MCMR-AAA-A | 9. PROCUREME | NT INSTRUMENT IDENTIFI | CATION | NUMBER | |
| 8c. ADDRESS (City, State, and ZIP Code) | | | 10. SOURCE OF | FUNDING NUMBERS | | | |
| 829 Chandler Street Fort Detrick, MD 21702-50 | 009 | 1 | PROGRAM ELEMENT NO. | PROJECT NO. | TASK NO. | | WORK UNIT ACCESSION NO. |
| | | | 63787A | 3016287A878 | 0 | F | DA360347 |
| 11. TITLE (Include Security Classification) Flight Evaluation of the Part 2: Questionnaire Da | | | g in the C | H-58D Helicopt | er, | | |
| 12. PERSONAL AUTHOR(S) Barbara A. Murphy and Be | en T. M | lozo | | | | | |
| 1111 | Bb. TIME CO | OVERED TO | 14. DATE OF RE 1999 Oct | PORT <i>(Year, Month, Day)</i> tober | 15. P/ | AGE COL 97 | TNT |
| 16. SUPPLEMENTAL NOTATION | | | | | | | |
| 17. COSATI CODES | | 18. SUBJECT TERMS (Co | ontinue on reverse if | necessary and identify by blo | ock numbe | er) | |
| FIELD GROUP SUB-GR | OUP | | | | | | |
| | | 1 | | | | | |
| 19. ABSTRACT (Continue on reverse if necessare Aviators assigned to OH-5 assessment of the communitation is readily available. Integrated Systems (PM-AC assigned to OH-58D operate sample of users for evaluations of the continuous performs well during dail inadequate speech clarity this report, published settled to the continuous performance of the community performance of the communi | 58D helication e for i CIS) pu tional uating on and ly miss y and u eparate ent rep | dicopter operated as earplug (CEP) immediate field archased enough units. The objective of the effective of communication points and is continuous and is co | . The CEP ing. Durin CEPs to ou jective of ess of the problems in nsidered a n the Kiowa ne method a | is a low cost of FY97, Project that all aviate the study was current CEP con the OH-58D he viable solution Warrior helicand assessment | and sors on the following to the followi | simpl ager- urren rm a ratio ter. the p . Pa ngs o | e approach Aircrew tly large n in The CEP roblem of rt 1 of f the |
| 20. DISTRIBUTION / AVAILABILITY OF ABSTRA | ACT AME AS RPT | . DTIC USERS | 21. ABSTRACT S Unclassif | SECURITY CLASSIFICATION | N | | |
| 22a. NAME OF RESPONSIBLE INDIVIDUAL Chief, Science Support Ce | enter | Pravious aditions are | (334) 255 | | MCMR | FICE SYM -UAX- | |

Preface

This work was funded by the Project Manager-Aircrew Integrated Systems (PM-ACIS). The authors would like to thank all the individuals involved in the installation of the Communications Earplug into the HGU-56/P helmets.

Table of contents

| | Page |
|-------------------------------------------------------|---------------------------|
| Background to questionnaire dataset | 1 |
| Questionnaire responses | 2 |
| Questions 1 thru 8 | 9 17 28 39 47 |
| Questions 34 thru 41 | |
| Questions 44 thru 45 | |
| Reference | 92 |
| Appendix | 93 |
| List of figures | |
| Figure 1. CEP integrated into HGU-56/P aviator helmet | 1 |

Background to the questionnaire data set

During FY 97, the Project Manager, Aircrew Integrated Systems (PM-ACIS) purchased enough Communications Earplugs (CEPs) to outfit all aviators currently assigned to OH-58D operational units. The CEPs were installed in HGU-56/P aviator helmets under the direction of PM-ACIS, with assistance provided by the U.S. Army Aeromedical Research Laboratory (USAARL). The acceptability of the CEP was assessed by asking aviators to compare the CEP helmet combination (Figure 1) with the helmet systems currently used in the OH-58D helicopter.

A novel questionnaire was constructed for this study (Appendix). The questionnaire consists of eight general sections: personal data, personal hearing protection, fitting, comfort, donning and doffing, speech clarity/understanding, noise reduction/attenuation, and general issues.

Part 1 of this report contains the details of the methods, analysis, and results of this survey research (Murphy and Mozo, 1999). This publication, Part 2, contains the data tables necessary to allow close inspection of individual subject responses




Figure 1. CEP integrated into HGU-56/P aviator helmet.

| | 80 | Seat | | Right | Right | Right | Right | Both | | Left and right | Left | Left | Right | | Left and right | Left and right | Right and left equal | Right | Left | Both | Fixed | Both | Right/pilot |
|-------------------------------------|-----|---------------------------|----|-------|-------|-------------------------------------------------------|-------|-------|-----|----------------|------|------|-------------------------------------------------|-----|----------------|----------------|----------------------|-------|-------|----------------------------------------------|--------------------------------------|-------|-------------------------------------------------------------------------------------|
| ter | 40 | Tip size | | short | std | std | std | short | std | short | std | std | std | std | Combo | std | std | short | short | slim | std | std | std |
| Evaluation in the OH-58D Helicopter | Q6a | CEP still functioning | | 1 | | 0 Plastic post attached to left ear piece snapped off | 1 | - | | | 1 | - | 0 Screw-tip portion broke off on right ear plug | - | _ | - | | 1 | 1 | 0 Because it broke at ear cushion connection | 0 Right earplug broke off from cable | - | 0 One of the troops crew chiefs thought they were just earplugs then just lost them |
| the OH | 90 | Flight hours using CEP | | | | | 20 | 100 | 200 | | 09 | 250 | 80 | 150 | 200 | 200 | 125 | | 125 | 25 | 250 | 100 | S |
| ation in | 65 | Flight hours using HGU-56 | | 300 | 120 | 009 | 300 | 20 | 400 | 300 | 65 | | 100 | 350 | 300 | 240 | 225 | 150 | 150 | 20 | 200 | 120 | 969 |
| Evalua | | Experience ight Hours | | 1000 | 420 | 2200 | 1700 | 009 | 009 | 1000 | 200 | 200 | | 200 | 1500 | 440 | 250 | 009 | 1500 | 1500 | 640 | . 365 | 700 |
| ight | Q4 | Aviator E Years Fli | | 7 | 3 | 10 | 9 | 3 | 3 | 4 | 7 | 7 | | 4 | ∞ | 2 | 3 | 4 | = | 7 | æ | 2 | 4 |
| EP Flig | 63 | Gender | | Σ | Z | × | × | Σ | × | Σ | Σ | Σ | Σ | Σ | Z | × | Σ | Σ | Σ | Σ | Σ | Σ | Σ |
| C | 01 | ID Num | | - | 7 | ъ | 4 | 2 | 9 | 7 | ∞ | 6 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 16 | 20 |
| | QI | Unit location | 1. | | | | | | | | | | | | | | | | | | | | |

¹ For the Yes/No questions, "Yes"=1 and "No"=0

| Q8 Seat | position | Left and right Right | Both | | | Right | Right | Standard | Split duties right and left. | R/L | Right | Left or right | Right | Both | Left | Left | Left | Left | Both | Right | Right | Right |
|------------------------------|-------------------------|-------------------------|------|----|----------------------------------------------------------------------------------------------------|-------|-------|----------|------------------------------|-------|-------|---------------|-------|------|------|-------------------------------------------------|--------------|------|------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------|----------------------------------------|
| Q7 Tin | size | std | std | | std | std | std | std | std | short | std | std | std | std | std | std | std | std | std | std | std | std |
| Q6a CEP still functioning | Simple and the training | 1 | _ | | Left earplug separated at earplug housing from wire during NBC flight. | - | - | _ | - | - | - | - | - | | - | 0 My original pair broke. I'm on my third pair. | 0 Wire broke | - | O Ear portion and cord became separated when caught up in the survival vest during | 0 Screw tip broke off | 0 Left wire into speaker is loose and sound comes in and out | 0 Intermittent operation on right side |
| Q6 Flight hours | using CEP | 110 | 20 | | 200 | | 150 | | | 250 | 200 | 100 | | 300 | 80 | 300 | 300 | 250 | 100 | 20 | | |
| Q5 Flight hours | using HGU-56 | 50 | 100 | | | 300 | 400 | 120 | 400 | 300 | 200 | 400 | 100 | 100 | 120 | | 300 | | 70 | 400 | 25 | 225 |
| Experience | Flight Hours | 500 900 | 350 | | 430 | 750 | 530 | 200 | 006 | 006 | 1000 | | 200 | 850 | 820 | 1200 | 2000 | 200 | 750 | 059 | 750 | 400 |
| Q4 Aviator Ex | Years Flig | 2 5 | 8 | | 7 . | 4 | 4 | e | S | S | 9 | 4 | 3 | 4 | 7 | 9 | 10 | 2 | •S | 4 | 'n | 2 |
| Q3 Gender | | ΣΣ | Σ | | Σ | Σ | Σ | Σ | Σ | į. | Σ | Σ | Σ | Σ | Σ | Σ | Σ | Σ | Σ | × | Σ | Σ |
| <u>1</u> 5 | Num | 21 | 23 | | - | 2 | 3 | 4 | 5 | 9 | 7 | ∞ | 6 | 10 | = | 12 | 13 | 14 | 15 | 16 | 17 | 81 |
| 21 Unit location | | 1. | ì | ~; | | | | | | | | | | | | | | | | | | |

| Q1 Unit location | Q1 ID Num | Q3 Gender | Q4 Aviator Ex | or Experience Flight Hours | Q5 Flight hours using HGU-56 | Q6 Flight hours using CEP | Qба CEP still functioning | Q7. Tip size | Q8 Seat position |
|---------------------|-----------------|--------------|---------------|-------------------------------|------------------------------------|---------------------------------|----------------------------------------------------------------------------------------------------------------------------|--------------------|------------------------|
| 2. | 61 | M | 3 | 550 | 75 | | 0 Wires broke away from ear | std | |
| | 20 | Σ | 'n | 700 | 230 | 180 | piece . | Combo | Right/left equal |
| 3. | | | | | | | | | make training. |
| | _ | Ľ | . 2 | 400 | 150 | - | | std | Left |
| | 7 | Σ | 9 | 2300 | 150 | 100 | 1 After one repair of broken stem | std | R/L |
| | 3 | Σ | 10 | 1600 | 400 | 300 | 1 | std | Right |
| | 4 | Σ | 4 | 200 | . 150 | | 1 | slim | Left |
| | S | Σ | . 2 | 800 | 109 | | - | std | Right |
| | 9 | Σ | 9 | 1200 | 200 | 200 | 1 | slim | Right |
| | 7 | Σ | 5 | 006 | 100 | 200 | | short | Right |
| | ∞ ′ | Σ | 4 | 1200 | 70 | | 0 The foam earplugs broke off after first use. ALSE repaired and it took about 5 more flight hours before they broke again | std | Right/left |
| | 6 | Σ | 01 | 1500 | 200 | 200 | - | std | Right |
| | 10 | Σ | 2 | 200 | 20 | 250 | | std | Right/Left |
| | = | Σ | 2 | 200 | 100 | 200 | 1 | std | Right |
| | 12 | Σ | 9 | 1250 | 250 | 15 | 1 | std | N/A |
| | 13 | Σ | 13 | 3300 | 400 | | Wire broke on one side where wire connects to plug itself. | std | Right |
| | 14 | Σ | 2 | 650 | 200 | | - | std | Both left and right0 |
| | 15 | Σ | 10 | | 30 | 9 | | std | Upright |
| | 91 | Σ | 10 | 2100 | 70 | 5 | 1 | std | Right |
| | 17 | Σ | e | 450 | 0 | 0 | Bong and whistles are too damned loud | std | Right |
| 4 | | ; | , | 000 | | | | , | ļ |
| | and . | Σ | 4 | 800 | | | - | stq | Right |
| | 7 | Σ | 2 | 430 | 150 | 20 | - | std | Upright |

| Q1 | Ŏ | 03 | 40 | | 95 | 90 | Q6a | 07 | 80 |
|---------------|-----------|--------|-----------------|-----------------------------------------|---------------------------|------------------------|---------------------------------------------------------------------------------------------|-------------|------------------------|
| Unit location | ID Num | Gender | Aviato Years | Aviator Experience ears Flight Hours | Flight hours using HGU-56 | Flight hours using CEP | CEP still functioning | Tip size | Seat position |
| 4. | | | | | | | | | |
| | 3 | M | 4 | 1200 | 40 | | | std | |
| | 4 | Σ | S | 1100 | 200 | | part | slim | Right |
| | \$ | M | 4 | 550 | 20 | | - | short | Left seat |
| | 9 | Σ | 4 | 029 | 100 | | _ | slim | Both |
| | 7 | Μ | 6 | 1600 | | 70 | | | Right seat |
| | ∞ | M | 2 | 1000 | 09 | 40 | _ | std | Yes |
| | 6 | Σ | 2 | 300 | 20 | | - | std | Left |
| 5. | | | | | | | | | |
| | - | M | - | 499 | 6 | | | short | Left |
| | 7 | ĭ | 2 | 1000 | | 200 | - | std | Right |
| | 3 | Σ | 6 | 2300 | 250 | | . Daniel | std | Left |
| | 4 | | - | 250 | 240 | 10 | _ | std | Left |
| | S | Σ | 2 | 400 | 20 | 10 | _ | | Equally left and right |
| | 9 | M | \$ | 029 | 15. | | - | std | |
| | 7 | Σ | S | 800 | 100 | | - | std | Left |
| | 00 | M | 3 | 400 | 01 | 100 | yand | std | Left/right |
| | 6 | Σ | 17 | 2000 | | 30 | - | std | Both |
| | 10 | Σ | 2 | 400 | 20 | 20 | . | std | Left and right equally |
| | = | Σ | 3 | 400 | 9 | | | short | Right |
| | 13 | | 6 | 2500 | 40 | 125 | 0 Left earplug intermittent, possibly due to wire breaking. ALSE issued me a new CEP. | slim | Left |
| | 13 | M | 4 | 290 | 40 | 9 | _ | std | Equal both seats. |
| | 14 | M | 2 | 400 | 120 | 2 | 1 | | Right |
| | 15 | M | 3 | 200 | 50 | 10 | 1 | std | Right |
| | . 91 | Σ | 15 | 2500 | | 01 | | std | |

| Q1 Unit location | Q1 ID Num | Q3 Gender | Q4 Aviator E Years Fli | Experience light Hours | Q5 Flight hours using HGU-56 | Q6 Flight hours using CEP | Qбя CEP still functioning | Q7 Tip size | Q8 Seat position |
|---------------------|-----------------|--------------|------------------------------|---------------------------|------------------------------------|---------------------------------|--------------------------------------------------|-------------------|---------------------------------|
| 6. | - | Σ | 9 | 1100 | 200 | 300 | None | t d | N/A |
| | 2 | Σ | 6 | 2200 | 400 | 200 | None | short | Right |
| | 3 | Σ | 2 | 200 | 50 | | 1 | std | Left |
| | 4 | Σ | 00 | 725 | 275 | 125 | 1 | slim | Left |
| | 2 | Σ | 9 | 750 | | | Earplug broke off at tip. | short | Left and right |
| | 9 | Σ | 13 | 3100 | 150 | 150 | 1 | std | Left |
| | 7 | Σ | S | 1000 | 100 | | 1 | std | Both |
| | ∞ | Σ | 9 | 1400 | | 100 | - | std | Left and right |
| | 6 | Σ | 9 | 1200 | 200 | | 1 | std | Left and right |
| | 10 | Σ | 10 | 2100 | 009 | 4 | - | | Right |
| 7. | | | | | | | | | |
| | 1 | Ľ | 4 | 200 | 100 | 20 | , quant | slim | Left/right |
| | 2 | Z | 5 | 1115 | | | 1 | std | Left |
| | ю | Σ | 3 | 400 | 5 | 110 | 1 | short | Right |
| | 4 | Σ | 2 | 470 | 100 | | 1 | short | Both equally |
| | S | Σ | 15 | 4000 | 200 | 200 | _ | slim | OH-58D(I) has one seat position |
| | 9 | Σ | 9 | 1000 | 800 | 200 | 1 | slim | Left and right |
| | 7 | Σ | 10 | 1700 | 200 | | | std | Either |
| | ∞ | Σ | 4 | 550 | 150 | | part | std | Both |
| | 6 | Σ | 9 | 1400 | 200 | 150 | 0 Wires broke | slim | Left |
| | 10 | Σ | 7 | 1350 | 20 | | - | std | Left |
| | 11 | Ĭ | 4 | 006 | 100 | 200 | 0 Broken wire, broken earplug tip | p std | Left/right |
| | 12 | Σ | 2 | 400 | 200 | | Broken wire and earplug tip. | std | Left/right |
| | 13 | Σ | ∞ | 2700 | 300 | . 250 | _ | std | Either of the two front seats |
| | 4 | Σ | ∞ | 1200 | 150 | | - | std | OH-58D(I) the only position |

| Q1 Unit location | Q1 ID Num | Q3 Gender | Q4 Aviator E Years Fli | or Experience Flight Hours | Q5 Flight hours using HGU-56 | Q6 Flight hours using CEP | Q6a CEP still functioning | Q7 Tip size | Q8 Seat position |
|---------------------|-----------------|--------------|------------------------------|-------------------------------|------------------------------------|---------------------------------|--------------------------------------------|-------------------|------------------------|
| 7. | 15 | Σ | 2 | 009 | 200 | | Wire keeps breaking from the foam earplug. | std | right |
| | 16 | Σ | 9 | 006 | 200 | 150 | | short | Both |
| | 17 | Σ | 9 | 1200 | | | | std | Both |
| | 18 | Σ | 4 | 550 | 400 | | 1 | std | |
| | 19 | Σ | ∞ | 850 | 150 | 200 | 1 | std | Left |
| | 20 | Σ | ∞ | 1400 | - | 200 | - | std | Left/right |
| | 21 | Σ | 15 | 3200 | 20 | 100 | 1 | std | Equal |
| | 22 | Σ | 9 | 1200 | 200 | 150 | | std | Right |
| | 23 | Σ | 9 | 006 | 12 | | 1 | std | Left |
| œ. | | | | | | | | | |
| } | - | M | 30 | 10500 | | 250 | 1 | slim | Left and right |
| | 2 | Σ | ∞ | 2400 | | 400 | - | std | Left |
| | 3 | Σ | 10 | 2200 | | 200 | _ | short | Equally left and right |
| | 4 | Μ | 14 | 4500 | 300 | 90 | _ | | Pilot or copilot |
| | S | Σ | 01 | 2700 | 9 | | 1 | std | Left |
| | 9 | M | 81 | | | | | | |
| | 7 | | 6 | 2700 | 2300 | | | std | Seat does not move |
| | ∞ | Σ | 91 | 4000 | | 250 | - | short | Both pilot and copilot |
| | 6 | X | 16 | 4500 | | 20 | - | std | Left seat |
| | 10 | Σ | 7 | 1800 | | 20 | 1 | | Equal |
| | 11 | Σ | ∞ | 2500 | | 200 | 1 | std | Left |
| | 12 | Σ | 15 | 4500 | | 200 | anne | std | Left and right |
| | 13 | Σ | 9 | 0001 | | | 1 Twice broken/ shorted wire | slim | Both |
| | 14 | Σ | 11 | 2000 - | | 20 | , mark | short | Right and left |
| | 15 | Σ | 91 | 5400 | | 20 | - | std | Left |

| Q1 Unit location | <u>o</u> | Q3 Gender | Q4 Av | 94 Aviator Experience | rience | Q5 Flight hours | Q6 Flight hours | | Q6a CEP still functioning | Q7 Tin | Q8 Seat |
|---------------------|---------------|------------------------------------|---------------|--------------------------|--------------------|--------------------|--------------------|---|-------------------------------|-----------|----------------|
| | Nun | | Years | 's Flight | Flight Hours | using HGU-56 | using CEP | , | Still tunctioning | size | position |
| ∞: | | | | | | | | | | | |
| | 91 | Σ | 7, | | 1600 | 1300 | 300 | | - | slim | Left |
| | 17 | M | • | | 1700 | 250 | 20 | | - | std | Left and right |
| 9. | | | | | | | | | | | 0 |
| | 1 | Σ | | _ | 200 | 50 | | | _ | slim | L/R |
| | 2 | Σ | • | _ | 1200 | 100 | 150 | | 1 | std | Right seat |
| | 3 | Σ | 51 | • | 3400 | 25 | 200 | | 0 Dead right plug | std | Left |
| | 4 | Σ | ` ' | • | 200 | 200 | 300 | | _ | slim | Both |
| | S | Z | 7 | _ | 009 | 250 | 150 | | | std | Right |
| | 9 | Σ | | _ | 240 | | 70 | | 1 | std | Both |
| | 7 | Σ | ĭ | | 4100 | 2 | 400 | | | std | Both |
| | ∞ | Σ | _ | ,, | 1000 | 100 | . 20 | | 1 | short | Left |
| | 6 | Σ | , , | • | 350 | 10 | 4 | | 1 | std | Left |
| | 10 | M | 11 | 6) | 3000 | 100 | 50 | | 1 | std | Both |
| | 11 | M | - | _ | 1800 | | 10 | | 1 | std | Right |
| | 12 | Σ | = | 15 | 1300 | 15 | 10 | | 1 | std | Fixed |
| | 13 | M | | 10 | 200 | 150 | 50 | | 1 | short | Even split L/R |
| | 14 | Σ | 7 | | 800 | 20 | 150 | | 1 | short | Right |
| | 15 | Σ | • | _ | 009 | 01 | 10 | | - | slim | Left |
| | 91 | Σ | . , | ~ | 200 | | | | 1 | short | |
| 10. | | | | | | | | | | | |
| | | M | | | 750 | | 150 | | 1 | std | Right and left |
| | Overall Total | M = 146 $F = 3$ $NR = 3$ $N = 152$ | Sum 96 Avg | 963.5 19 6.4 | 199414.0 1347.4 | Avg 205.3 | Avg 129.4 | | Yes = 126 N = 23 NR = 3 | : | |

| | | | | | | The state of the s | | | |
|---------------------|-----------|------------------------------|------------------------------|----------------|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Q1 Unit location | QI Num | Q9 Waiver or IO letter | Q10 Fly with spectacle | Spectacle type | Q11 Wear earplugs with helmet | Q12 Discomfort w/earplugs - onset and description | nplugs - ption | Q13 Discomfort w/ helmet - onset and description | helmet - onset |
| ن ا | | | | | | | | | |
| | - | 0 | 0 | | | _ | Lack of ICS volume | 0 | |
| | 7 | 0 | 0 | | | 1 2-3 hours, combined w/ hearing difficulty | oined Pain culty | 1 3-4 hours | Hot spots, headaches |
| | 9 | 0 | 0 | | 1 | 0 | | 0 | |
| | 4 | 0 | 0 | | 1 | 0 | | 0 | |
| | 2 | 0 | 0 | | 1 | 0 | | 0 | |
| | 9 | | 0 | | 0 | | | 0 | |
| | 7 | 0 | 0 | | 1 | 0 | | 0 | |
| | 00 | 0 | 1 | Bayonet | - | 0 | | 0 | |
| | 6 | 0 | 0 | | 1 | 0 | | 0 | |
| | 10 | 0 | 0 | | 1 | 0 | | 0 | |
| | Ξ | 0 | 0 | | 1 | Only until I bream in | Only until I break them Slight pain in | 0 | |
| | 12 | 0 | 0 | | - | 0 | | 0 | |
| | 13 | 0 | 0 | | - | 0 | | 0 | |
| | 14 | 0 | 0 | | - | 0 | | 0 | |
| | 15 | 0 | 0 | | 0 | y | Pain in the car can | 0 | |
| | 16 | 0 | 0 | | 0 | | | 0 | |
| | 11 | 0 | 0 | | 0 | 1 Few hours | dull pain, continuous after a few days flying | 0 | |
| | <u>®</u> | 0 | o , | | - | 0 | | I 30 minutes | s Sometimes just slight discomfort from the size of the speaker; other times it felt as though the plastic portion of the plug was contacting my ear canal. |
| | 61 | 0 | 0 | | - | | | 0 | |
| | 20 | 0 | 0 | | | 1 2 hours | Itching, sweating 0 | 0 2 | |

| Q1 Unit location | P U W | Q9 Waiver or IO letter | Q10 Fly with spectacle | Spectacle type | Q11 Wear earplugs with helmet | Q12 Discomfort w/earplugs - onset and description | - 55 | Q13 Discomfort w/ helmet - onset and description |
|---------------------|-------|------------------------------|------------------------------|-------------------|-------------------------------------|---------------------------------------------------|-----------------|--------------------------------------------------|
| 1. | | | | | | | | |
| | 21 | 0 | 0 | | 1 | 0 | | 0 |
| | 22 | 0 | 0 | | _ | .0 | | · · · |
| | 23 | 0 | 0 | | 1 | 0 | | · · · |
| 2. | | | | | | | | |
| | 1 | 0 | 1 | Wire frames | - | 0 | | 0 |
| | 7 | 0 | 0 | | - | _ | Itchiness | 0 |
| | 3 | 0 | 0 | | 1 | 0 | | 0 |
| | 4 | 0 | 0 | | 0 | | | 0 |
| | 2 | 0 | 0 | | 0 | 0 | | 0 |
| | 9 | 0 | 0 | | 1 | 1 3-4 hours | Itchiness, pain | 0 |
| | 7 | 0 | 0 | Sunglasses | - | 0 | | 0 |
| | | | | day | | | | |
| | 00 | 0 | - | Cable | | 0 | | 0 |
| | 6 | 0 | 0 | | - | 0 | | 0 |
| | 10 | 0 | 0 | | - | 0 | | 1 2.5-3.0 hrs Hot spot |
| | | | | | | | | under NVG only |
| | 11 | 0 | 0 | | | 0 | | 1 I hour Hot snots |
| | 12 | 0 | 0 | | | 0 | | |
| | 13 | 0 | 0 | | 0 | | | 0 |
| | 14 | 0 | 0 | | | 0 | | 0 |
| | 15 | 0 | 0 | | 1 | 1 2-3 hours | Aching in inner | 1 2-3 hours Hot spot on top of head. |
| | | | | | | | cal | Bottom of earcups chafe neck |
| | 16 | 0 | 0 | | 1 | 0 | | 0 |
| | 17 | 0 | 0 | | 1 | 0 | | 1 45 minutes Hot spots |
| | 18 | 0 | 0 | | | 0 | | 0 |

| Q1 Q1 Unit location ID | 91 Num | Q9 Waiver or IO letter | Q10 Fly with spectacle | Spectacle type | Q11 Wear earplugs with helmet | Q12 Discomfort w/earplugs - onset and description | w/earplugs | | Q13 Disco | Q13 Discomfort w/ he and description | Q13 Discomfort w/ helmet - onset and description |
|---------------------------|-----------|------------------------------|------------------------------|-------------------|-------------------------------------|---------------------------------------------------|------------|-----------------------------------|--------------|--------------------------------------|--------------------------------------------------|
| 2. | 19 | 0 | 0 | | 1 | 0 | | | - | Beginning | Pain inside ear opening |
| | ; | • | | | | ı | | | | | • |
| | 20 | 0 | 0 | | · - | 0 | | | - | 1-2 hours with NVGs, 3-4 hours | Hot spot top of my head |
| 3. | | | | | | | | | | | |
| | - | 0 | 0 | | 1 | 1 30 minutes | | itch | _ | 30 minutes hotspots | hotspots |
| | 7 | 0 | - | Bayonet | 1 | 0 | | | 0 | | |
| | ю | 0 | 0 | | 1 | 0 | | | 0 | | |
| | 4 | 0 | 0 | | - | 1 | | | 0 | | |
| | 2 | 0 | 0 | | | 0 | | | 0 | | |
| | 9 | 0 | 0 | | | 0 | | | 0 | | |
| | 7 | 0 | 0 | | | 0 | | | - | 2 hours | hotspots usually associated with NVGs |
| | 00 | 0 | 0 | | - | 0 | | | 0 | | |
| | 6 | 0 | 0 | | 1 | 0 | | | 0 | | |
| | 10 | 0 | 0 | | - | 0 | | | 0 | | |
| | 11 | 0 | 0 | | 1 | 0 | | | - | 2 hours | hotspot |
| | 12 | 0 | 0 | | 0 | | | | 0 | | |
| | 13 | 0 | 0 | | _ | 0 | | | 0 | | |
| | 14 | 0 | 0 | | - | 0 | | | 0 | | |
| | 15 | 0 | 0 | | 1 | 0 | | | 0 | | |
| | 91 | 0 | | | - | 0 | | | 0 | | |
| | 17 | 0 | 0 | | 1 | 0 | | | 0 | | |
| 4. | | | | | | | | | | | |
| | _ | 0 | 0 | | 1 | 1 15-20 minute immediately. | s if not | The plastic core presses into the | 0 | | |

| Q1 Unit location | 56 | Q9 | Q10 | 5 | 011 | 012 | | Q13 | |
|---------------------|----------|----------|-----------------------|-------------------------------------|------------------------------|------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|--------------------------------------|
| Oille location | Num | | riy with spectacle | Spectacie type | Wear earplugs with helmet | Discomfort w/earplugs - onset and description | | Discomfort w/ helmet - onset and description | helmet - onset |
| 4 | | | | | | | | ļ | |
| | 7 | 0 | 0 | • | 1 | 1 Varies | Itchiness, | 0 | |
| | | | | | | | uncomtortable, slipping | | |
| | e | 0 | 0 | | | | | 0 | |
| | 4 | 0 | 0 | | _ | 0 | | | |
| | \$ | 0 | - | Bayonet temples, wire frames. | 1 | 1 About 3 hours | Pain in upper ear. 0 | . 0 | |
| | 9 | 0 | 0 | | - | 1 Varies from 15 minutes Itchiness with a to 1 hour. | es Itchiness with a lot of discomfort. | _ | 15 minutes Hot spot on forehead. |
| | 7 | 1 1 year | 0 | | 0 | | | c | |
| | ∞ | 0 | 0 | | _ | - | Itchinese nain | 1 1 1 | Hot enote beadeate |
| | 6 | 0 | 0 | | _ | 0 | · · · | 1 Soon | Hot spots, neguacine |
| 5. | | | | | | • | | 1000 | riot spots |
| | _ | 0 | 0 | | - | 0 | | 0 | |
| | 7 | 0 | 0 | | - | 0 | | 0 | |
| | က | 0 | 0 | | 0 | 0 | | _ | Headaches (noise |
| | 4 | 0 | 0 | ٠ | 1 | 0 | | . 0 | ocion) concentrati |
| | 2 | 0 | 0 | | 1 | 0 | | 1 30 minutes | 30 minutes Hot snot on ton of helmet |
| | 9 | 0 | 0 | | 1 | 0 | | | to the charge of the manner. |
| | 7 | 0 | 0 | | _ | 1 As soon as I put them in. | Pain - the foam earplugs when screwed in - the screwed in part stabs my ear so I can't place the foam part as far in as I like too. | 0 | |
| | ∞ | 0 | 0 | | 0 | 0 | | 1 1 hour | Hot spots on forehead, headaches |
| | 6 | 1 | 0 | | | 1 After a couple of adjustments I could fix | Pain x | | |

| Q1 Unit location ID | QI ID Num | Q9 Waiver or IO letter | Q10 Fly with spectacle | Spectacle type | Q11 Wear earplugs with helmet | Q12 Discomfort w/earplugs - onset and description | | Q13 Discomfort w/ h and description | rt w/ he ption | Q13 Discomfort w/ helmet - onset and description | |
|------------------------|-----------------|------------------------------|------------------------------|-------------------|-------------------------------------|---------------------------------------------------|----------------------------|-------------------------------------|-------------------|--------------------------------------------------|---|
| | | | | | | | | | | | • |
| | 10 | 0 | 0 | | 1 | 0 | | | | | |
| | 11 | 0 | 0 | | _ | 0 | | | | | |
| | 12 | 0 | 0 | | 1 | 1 Itchiness | ness | 0 | | | |
| | 13 | 0 | 0 | | 1 | | | 1 3 hours | | Hot spots | |
| | 14 | 0 | 0 | | 0 | | | 0 | | | |
| | 15 | 0 | 0 | | 1 | 0 | | 0 | | | |
| | 16 | 0 | 0 | | _ | 0 | | 0 | | | |
| | | | • | | | | | | | | |
| | _ | 0 | 0 | | 0 | | | 0 | | | |
| | 7 | 0 | 1 | Strap | 0 | | | 0 | | | |
| | 60 | 0 | 0 | | - | I Dull | Dull pain. Some itchiness. | 1 2 hours | | Head itches. | |
| | 4 | 0 | 0 | | 1 | 0 | | 0 | | | |
| | 2 | 0 | - | | | 0 | | 0 | | | |
| | 9 | 0 | 0 | | - | 0 | | 0 | | | |
| | 7 | 0 | . 0 | | - | 0 | | 0 | | | |
| | • | 0 | 0 | | - | 0 | | 0 | | | |
| | 6 | 0 | 0 | | 1 | 0 | | 0 | | | |
| | 10 | 0 | 0 | | 1 | 0 | | 0 | | | |
| | | | | | | | | | | | |
| | | 0 | 0 | | 0 | . 0 | | 0 | | | |
| | 7 | 0 | 0 | | - | 0 | | 0 | | | |
| | 3 | 0 | 0 | | _ | 0 | | 0 | | | |
| | 4 | 0 | 0 | | 1 | 0 | | 1 30 m | ninutes | 30 minutes hot spots | |
| | S | 0 | _ | Comfort | 0 | | | 0 | | | |
| | | | | around) | | | | | | | |
| | 9 | 0 | 0 | | | 0 | | 0 | | | |

| 01 | 5 | 60 | | Q10 | | Q11 | Q12 | | 013 | | |
|---------------|-----|-------------|------------------------|--------------------|-----------------------|---------------------------|-----------------------------------------------|-------------|----------------|---------------------------------|------------------------------------------------------|
| Unit location | Num | Wai IO I | Waiver or IO letter | Fly with spectacle | Spectacle type | Wear earplugs with helmet | Discomfort w/earplugs - onset and description | - S6 | Disco and d | Discomfort w/ I and description | Discomfort w/ helmet - onset and description |
| 7. | | | | | | | | | | | |
| | 7 | - | In process | - | Bayonet | - | 0 | | - | After 1.5 | Hot spot |
| | c | < | | • | | • | | | | hours | |
| | × | > | | 0 | | 0 | 0 | | 0 | | |
| | 6 | 0 | | 0 | | 1 | 0 | | 0 | | |
| | 10 | 0 | | 0 | | 0 | . 0 | | 0 | | |
| | 11 | 0 | | 0 | | 0 | | | 0 | | |
| | 12 | 0 | | 0 | | _ | 0 | | 0 | | |
| | 13 | 0 | | 0 | | - | 0 | | Ó | | |
| | 14 | 0 | | _ | Wire | _ | 0 | | 0 | | |
| | 15 | 0 | | 0 | | 0 | | | 0 | | |
| | 16 | 0 | | 0 | | - | 0 | | 0 | | |
| | 17 | 0 | | 0 | | 0 | 1 2 hours | Itching | - | 1 hour | |
| | 18 | 0 | | _ | | 0 | |) | | | |
| | 19 | 0 | | 0 | | _ | 0 | | 0 | | |
| | 70 | 0 | | _ | Wire frame | _ | 0 | | 0 | | |
| | | | | | Ray-Ban sunglasses | | | | | | |
| | 21 | 0 | | 0 | | 1 | 0 | | 0 | | |
| | 22 | 0 | | 0 | | 1 | . 0 | | - | 1/2 hour | Hot spots and headache. |
| | | | | | | | | | | | Just don't like that style helmet. Too big and hulky |
| ć | 23 | 0 | | 0 | | 1 | 0 | | - | 1 minute | Could not hear! |
| x i | - | - | 16 years | - | Bayonet temples | 1 | 0 | | 0 | | |
| | 7 | 0 | | 0 | | _ | 0 | | 0 | | |
| | 3 | 0 | | 0 | | - | 0 | | 0 | | |
| | 4 | 0 | | 0 | | 1 | 1 Within 45 minutes | Poking pain | 0 | | |

| - onset | | | | | Hot spot top center of forehead. | | | | | | | | | | | | | | | | oots | |
|---------------------------------------------------|------------------|---|--------------------------------------|----|----------------------------------|---|---------|----|-----------|----|---------------------------------------------------|----|-------------|----|-----|------------|-------------|---|---|----|-----------|---|
| helmet | | | - e | | Hot s | | | | | | | | | | | | | | | | Hot spots | |
| Q13 Discomfort w/ helmet - onset and description | | | I did after I tried to use it. | | 1 hour | | | | | | | | | | | | | | | | 1 hour | |
| Q13 Disc | ٥ | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | al. 0 | 0 | 0 | • | > < | • | 0 | 0 | 0 | 0 | | • |
| | Ear pain | | | | | | | | pain | | Pain in ear canal. Full feeling in my head. | | | | | | | | | | | |
| Q12 Discomfort w/earplugs - onset and description | About 30 minutes | | | _ | | | | | 2-3 hours | | 5-10 minutes | | | | | | | | | h_ | | |
| | · - | 0 | 0 | 0 | 0 | 0 | 0 | | - | 0 | - | 0 | 0 | - | • | 0 | 0 | 0 | 0 | 0 | 0 | C |
| Q11 Wear earplugs with helmet | - | 1 | 0 | 1 | 1 | - | 0 | - | _ | - | 0 | _ | - | _ | | | - | - | 1 | 1 | _ | |
| Spectacle type | | | | | | | | | | | | | Wire frames | | | | Wrap around | | | | | |
| Q10 Fly with spectacle | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | - | | 0 | _ | 0 | 0 | 0 | 0 | 0 |
| Q9 Waiver or IO letter | | | | • | | | 2 years | | | | | | | | | 8 years | | | | | | |
| | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | c | · c | · - | 0 | 0 | 0 | 0 | 0 | 0 |
| Num Num | 5 | 9 | 7 | 00 | 6 | 2 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | - | | l m | 4 | 3 | 9 | 7 | • | 6 |
| Q1 Unit location | % | | | | | | | | | | | | | .6 | | | | | | | | |

| Q1 Q1 Unit location ID Nu | Q ⊟ N Num | Q9 Waiver or IO letter | Q10 Fly with spectacle | Spectacle type | Q11 Wear earplugs with helmet | Q12 Discomfort w/earplugs - onset and description | Q13 Discomfort w/ helmet - onset and description |
|---------------------------------|--------------|------------------------------|-------------------------------|-------------------|-------------------------------------|---------------------------------------------------|--------------------------------------------------|
| 9. | | | | | | | |
| | 10 | 0 | 1 | Wire frames | 0 | 0 | C |
| | 11 | 0 | 0 | | 0 | | |
| | 12 | 1 | 0 | | 1 | I Itching nain | 1 45 minutes Hot enote |
| | 13 | 0 | 0 | | - | 0 | |
| | 14 | 0 | 0 | | +4 | 0 | |
| | 15 | 0 | 0 | | 1 | 0 | |
| | 91 | 0 | 0 | | - | 0 | |
| 10. | | | | | | | • |
| | - | 0 | 0 | | 1 | 0 | 0 |
| Overall Total N = 152 | N = 152 | Yes = 7 N = 145 NR = 0 | Yes = 17 N = 135 NR = 0 | | Yes = 121 N = 29 NR = 2 | Yes = 26 N = 110 NR = 16 | Yes = 27 N = 120 NR = 5 |

| 21 Jnit location | O UM | | iculty in fitting CEP | Q15 Discomfort inserting CEP | Q16 Wires when t | Q16 Wires pull on CEP when turning head | Q17 CEP durir | Q17 CEP move in/out of ear during flight |
|---------------------|----------|----|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|---------------------------------------|---------------------------------------------------------------------------------------------------------|---------------------|-----------------------------------------------------------------|
| | | | | | | | | |
| | | 0 | | 0 | 0 | | _ | Occasionally slips out of ear |
| | 2 | 0 | | 0 | 0 | | - | Sometimes w/ excessive head movement |
| | ы | 0 | | 0 | - P | Small Velcro piece becomes detached, hangs free and sways. | - | Backs out of ear canal if not fully seated. |
| | 4 | 0 | | 0 | L the second | Thy will get caught on anything from shoulder harnesses to flight suit collars | 0 | |
| | Ś | - | After washing them they lose their ability to stay crimped during insertion. | | 0 | | 0 | |
| | 9 | - | After repeated use they are difficult to slide in ears - not impossible though. | 0 | ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ | Sometimes during NVG flights, the wires get tangled with the NVG neck cord, power cord or battery pack. | - | Occasionally they will fall out of ear during long flight |
| | 7 | 0 | | The hard post rubs inside of ear. | 1 7 | If you make rapid head movements they tend to pull out. | - | After you start to sweat they come out of your ears. |
| | ∞ | - | Hard to get the CEP into the ear and have it stay in place. | There is not as much cushion as with the yellow foam ear plugs. | 1 1 | The wires catch on the vest | - | When you sweat the CEP slips out of ear |
| | 6 | 0 | | 0 | | The wires sometimes become caught on misc. items. | - | They sometimes get pulled down by wire or when I adjust helmet. |
| | 01 | 0 | | Housing creates a hard object which can press against the outer ear. | | | - | |
| | = | .0 | | 0 | , | If not attached high enough on the helmet the CEP wire catches on the helmets lower edge | 0 | |
| | 12 | - | Earplugs too large initially | 1 Plastic screw too long | 0 | | 0 | |
| | 13 | 0 | | _ | 7 2 | About 50% of the time I feel the wire pull when turning my head | - | Occasionally |
| | 14 | 0 | | 0 | 0 | | 0 | |
| | 15 | 0 | | | - | The wires get caught in the seatbelt or the Velcro strip on the wire gets caught on something | - | from the wire pulling on the earplug during flight |

| Q1 Q1 Unit location ID Nu | P D N | | Q14 Difficulty in fitting CEP | Q15 Discomfo | Q15 Discomfort inserting CEP | Q16 Wire when | Q16 Wires pull on CEP when turning head | Q17 CEP duri | Q17 CEP move in/out of ear during flight |
|------------------------------|-------|---|----------------------------------------|------------------|----------------------------------------------------------------------------|---------------------|-----------------------------------------------------------------------------------------------------------------------------|--------------------|------------------------------------------------------------------------|
| -: | 16 | - | Size adjustment. Needed short | 0 | | 0 | | 0 | |
| | 17 | 0 | | 0 | | | tangled around other wires | - | tangled around other wires or caucht on something |
| | 18 | 0 | | 0 | | _ | They tend to catch under my collar | | 9 |
| | 19 | 0 | | 1 Blunt canal | Blunt sharp edges on the CEP hurts ear canal | - | They snag on helmet or on flight suit and usually pull out of ear | - | They work themselves loose on long flights |
| | 20 | 0 | | 0 | | - | With the neck cord from the NVGs it sometimes pulls on the CEP cords | _ | Only if the helmet is moved |
| | 21 | - | Standard is too fat - slim is too slim | 1 Plastic | Plastic is hard - after 4-5 days of continuous use, ear canal is sensitive | 0 | | 0 | |
| | 77 | 0 | | 0 | | 0 | | c | |
| | 23 | 0 | | 0 | | 0 | | | |
| 2. | | | | | | | | , | |
| | - | 0 | | 0 | | - | Sometimes the wires get tangled with either the NVG battery pack, ODA, or even the seat belt taking a lot of the slack out. | 0 | |
| | 7 | 0 | | 0 | | 0 | | _ | Occasionally |
| | 33 | 0 | | 0 | | _ | | - | familia |
| | 4 | 0 | | 0 | | - | | 0 | |
| | S | 0 | | 0 | | - | Gets caught on the back of the vest especially during NVG flight when the wire won't stay Velcro. | - | After about 2 hours, especially on warm days when your start sweating. |
| | 9 | 0 | | 0 | | 0 | | 0 | |
| | 7 | 0 | | 0 | | - | Only while wearing NVGs and weight bag | 0 | |
| | ∞ | 0 | | 0 | | 0 | | 0 | |
| | 6 | 0 | | 0 | | 0 | | 0 | |
| | 10 | 0 | | 0 | | - | Occasionally, especially when wearing NVGs with the attached | 0 | |

| Q1 Q1 Unit location ID Nu | Q1 ID Num | | Q14 Difficulty in fitting CEP | Q15 Disc | Q15 Discomfort inserting CEP | Q16 Wire | Q16 Wires pull on CEP when turning head | Q17 CEP durin | Q17 CEP move in/out of ear during flight |
|---------------------------------|-----------------|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|--------------------------------------------------------------------|
| 2. | = | c | | ٥ | | _ | We mount to much theff on our | - | |
| | : | • | | > | | | we mount so much start on our head, the wires get intermixed | - | Once the toam inserts wear |
| | 12 | 0 | | 0 | | _ | Sometimes it catches on the other lanyards and wire connections I.e. NVGs, ODA, ICS cable. | 0 | |
| | 13 | 0 | | - | Until I get used to the feel of the plug | | | - | Because short wire pulled loose |
| | 41 | 0 | | 0 | | = | If I do not remember to keep the cord off my neck and over the survival vest it catches. A fix; create loop or Velcro hold to keep cord on helmet | 1 | If not inserted fully or hastily and the cord pulls - it comes out |
| | 15 | 0 | | _ | In the beginning the edges might catch my ear and after a while some mild aching inside the ear | - | Sometimes when caught on something. Mostly not. | - | Only infrequently did one slip out |
| | 91 | 0 | | 0 | | - | Sometimes when flying NVGs, while turning head CEP would get pulled out | 0 | |
| | 11 | 0 | | 0 | | _ | Not often. If it catches on my shirt | _ | It has. Installed in a hurry |
| | 18 | | After wearing the CEP for more than 20 minutes the foam tip would not stay compressed for reinsertion back into the ear. Heat and moisture would prevent this | - | Over time the foam tips would begin to itch | | Wires would frequently catch on objects and pull out of the ear at times | - | At times the foam tip would back out of the ear canal |
| | 19 | - | Will not stay in ear | _ | Same as above | _ | Wires are always in the way | - | At least slips out once on each flight |
| | 20 | - | Finding correct size foam insert and the diameter of the CEP itself | 0 | | 0 | | - | Occasionally |
| ę. | 7 | 0 0 | | 0 0 | | - 0 | | 0 0 | |

| 21 Jnit location | Q1 ID Num | | Q14 Difficulty in fitting CEP D | Q15 Discomfort inserting CEP | Q16 Wires CEP | Q16 Wires pull on CEP when turning | Q17 CEP duri | Q17 CEP move in/out of ear during flight | |
|---------------------|-----------------|-----|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|--------------------------------------------------------------------------------|--------------------|------------------------------------------------|---|
| | 3 | 0 | 0 | | - | When Velcro catches on battery pack on helmet or other places such | - | See #16 | _ |
| | 4 | 0 | 0 | | _ | as vest Well when turning head to left | - | See #16 | |
| | S | 0 | 0 | | | wires are pured. Some times because of the limited space within the A/C. | - | Sometimes when 'live fire" of weapons | |
| | 9 | 0 | | The plastic housing hurt my earlobe during 1 the first few weeks. I repositioned by turning and now I can fly 4 hours or so without discomfort | - | Only under NVG flying when I put the CEP in prior to putting on the NVG | 0 | | |
| | 7 | 0 | - | Occasionally I fell the hard portion of inner core against eardrum when I insert in earcanal | 0 | | 0 | | |
| | •• | 0 | 0 | | 1 | They get hung up on other things attached to my helmet | _ | See 16 | |
| | 6 | 0 | 0 | | 0 | | 0 | | |
| | 10 | 0 | 0 | | | Head turns more than 60 degrees left or right it often snags. | 0 | | |
| | = | 0 | 0 | | | Occasionally pull plugs out of ear | - | Occasionally pulled out of place | |
| | 12 | 0 | 0 | | - | Loose wire snags on things especially while wearing NVGs | _ | | |
| | 13 | 0 | 0 | | _ | Sometimes while turning head | 0 | | |
| | 14 | o · | | | _ | If the wires are not positioned directly behind my head, the wires get tangled | 0 | | |
| | 15 | 0 | 1 | The plastic center rubs the ear canal and is 1 very uncomfortable | _ | Wires too long and catch on ICS cord and other items such as survival vest | 0 | | |
| | 91 | 0 | 0 | | _ | | 0 | | |
| | 17 | - | When putting helmet on 0 CEP would move and cause discomfort | | - | | _ | When putting helmet on | |
| | | | | | | | | | |

| | The state of the last of the l | | | | | | | | |
|---------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|-----------------------------------------------------------------------------------------------------------|-------------|---------------------------------------------------------------------------------|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|
| Q1 Unit location | Q1 ID Num | | iculty in fitting CEP | Q15 Disc | Q15 Discomfort inserting CEP | Q16 Wire | Q16 Wires pull on CEP when turning head | Q17 CEP move in during flight | Q17 CEP move in/out of ear during flight |
| 4 | - | - | It goes - but intermittently it slides out and I have to continuously readjust the earplug throughout the | - | The plastic core. | | They slide out during any rapid head movements. | 0 | |
| | 7 | 0 | | 0 | | | Too short | 1 1 | Wires to short |
| | က | - | Difficult to fully put CEP in. Often the wires catch on NVG goggle cord/power supply cord. | _ | Pressing earplugs is sometimes painful | | Sometimes. See #14 | 1 2 E | Cord catches on other wire hamesses, etc. |
| | 4 | - | Too big | _ | Too big | _ | | - | |
| | ٠, | 0 | | 0 | | 0 | | 1 0 w | Once in awhile they slip out when I adjust my helmet. |
| | 9 | - | The first set was too big. | _ | They poke the sides of my ears. | _ | If cable catches on seat belts. | 1 S | Sweat works it out. |
| | 1 | 0 | | 0 | | - | Sometimes wire gets in between my collar and neck. The wire sticks to my skin and pulls. | 0 | |
| | ∞ | 0 | | 0 | | _ | Not too bad | z | Not too bad |
| | 6 | 0 | | - | Too deep | _ | Too short | 1 E | Fall out |
| ń | - | 0 | | 0 | | - | | _ _ \$ | I use the "shorts" which tend to pull out easily |
| | 2 | 0 | | _ | Until I got used to the plugs, they scraped your ear when putting them in. | 0 | | 0 | |
| | 3 | - | Difficult to put helmet on without moving ear plugs. | _ | Have to push them in deep in ear so they don't come out when putting helmet on. | 1 | Sometimes get caught on shoulder straps and vest. | 0 | |
| | 4 | 0 | | 0 | | - | Doesn't happen very often. The wires sometimes work themselves between the ALSE vest and the seatbelt/shoulder harness. When you turn your head, it pulls. | | |
| | S | 0 | | _ | It's a little big for my ear canals. | - | They catch on shoulder belts and survival vest behind me. | 0 | |

| Q17 CEP move in/out of ear during flight | | Same as #16. | | | | Only once in a while when the wires get caught | | Short wire sometimes. Why- unknown. I think it catches on the helmet or shoulder hamess or something | 0 | | | | | | Only sometimes. |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------|----|-----|------------------------------------------------------------------------------------------------------------------|----|-----|-----|----------------------------------------------------------|
| 00-5 | 0 0 | s 1 | 0 Jc | 0 | 0 | - | 0 | yand. | C | • • | 0 | | 0 | 0 | - |
| Q16 Wires pull on CEP when turning head | The CEP pulls due to wiring laying about the pilots shoulders/neck and coming into contact with other hardware - i.e. wires, seathelt. | Only sometimes. Out of 10 flights maybe three. | Minimal, due to extreme amount of plugs, wires, cables, vests and other misc. equipment jammed into a small cockpit. | Gets caught in my vest behind the helmet. | Only when it gets tangled with the communication plug-in. But if you plug into the aircraft last it doesn't cause a problem. | They get caught in the hamess straps or between my neck and collar. | At times, not always. | | | | Occasionally, not a big deal. | | | | With goggles and mic cord, the earplug cords get pulled. |
| Q16 Wire | - | - | _ | - | - | - | - | 0 | 0 | _ | - | | _ | 0 | - |
| Q15 Discomfort inserting CEP | | Explained in #12 | | | | After putting the helmet on, the CEP tends 1 to slip and I have to readjust them. | | | | | | | | | |
| Q15 Disc | 0 | 1 | o Se ce | 0 | • | - | 0 | 0 | 0 | 0 | too 0 ear ar. | • | - | 0 | 0 |
| Q14 Difficulty in fitting CEP | | Explained in #12 | The post is so large that slim/short foam tips cause discomfort resulting in use of the standard. | To long and a little stiff feeling inside the ear. | | | | | | | They seen to be slightly too long, pressure from the ear cup causes slight discomfort to the outer ear. | | | | |
| Q14 Diff | 0 | - | - | - | 0 | 0 | 0 | • | 0 | 0 | - | c | > < | 0 (| 0 |
| Num Num | 9 | 7 | ∞ | 6 | 10 | = | 21 | <u></u> | 14 | 15 | 16 | - | ٠, | 7 | m |
| Q1 Unit location | ۶, | | | | | | | | | | | ۰, | | | |

| Q1 Unit location | S Cl | Q14 Difficulty in fitting CEP | Q15 Disc | omfort inserting CEP | Q16 Wires pull on CEP when turning head | Q17 CEF duri | Q17 CEP move in/out of ear during flight |
|---------------------|----------|---------------------------------------------------------------------------------------|-------------|----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------------------------------------------------------------------------------------------------------------------------|
| | 4 | 0 | - | Occasionally the solid plastic portion will 1 scrape ear canal or be inserted too far. | Wires get hung up on numerous things (shoulder harness, NVG cable, mic boom, etc) | 1 | If adjusting helmet, tend to fall out. |
| | 2 | 0 | 0 | 0 | | 0 | |
| | 9 | 0 | o · | - | Once in a while when CEP/NVG power supply/ODA cables get twisted together. | 0 | |
| | 7 | 0 | 0 | 1 | | | Only if it gets snagged. |
| | ∞ | 0 | _ | If pushed in, the inner portion can be felt 1 against inside of ear. | Wires get caught on flight vest, | 0 | |
| | 6 | 0 | - | Tip would cause discomfort after 3-4 hours.0 | | 0 | |
| | 01 | 0 | - | They are uncomfortable | They catch on stuff. | 0 | |
| | - | 0 | 0 | - | | 0 | |
| | 7 | . 0 | 1 | I found the standard plugs to be too large 1 | | _ | Only during transition wear |
| | en . | 1 The earplugs were too long and they were touching my eardrum and causing pain | - | The discomfort is only present when the learplug is not properly in the helmet earcup | The wire gets caught on my vest or seatbelt and pulls a little, but it has not been a real problem | 0 | |
| | 4 | 0 | 0 | | Solution is to bundle the wire between the NVG weight pack and helmet Velcro, but it is still a pain. The wires get caught on the scatbelt guide and they can be pressed between your back and the seat | 1 | When the wire is caught on something while turning your head, an earplug can be pulled out of the ear. That's a real pain too |
| | S | 0 | - | Initial issue had standard size. Changed to 1 slim. | Drag across back of neck (especially when sweaty), sometimes catch on NVG cables or on flight suit collar. | y-well | From time to time - not always |
| | 9 | 0 | 0 | | Wires get caught on survival vest. | _ | A few times during flight my CEP has fallen out of my ear. |
| | 7 | 0 | - | The sharp edges on the exterior piece. | Ear cushions press against head, can feel pulling of wires when turning head. | 0 | |
| | ∞ | 0 | 0 | | | 0 | |

| Q1 Q14 ID Diff Num | Q14 Difficulty in fitting CEP | Q15 Discomfort inserting CEP | Q16 Wire | Q16 Wires pull on CEP when turning head | Q17 CEP durin | Q17 CEP move in/out of ear during flight |
|--------------------------|--------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-------------|----------------------------------------------------------------------------------------------------------------|---------------------|--------------------------------------------------|
| | Sometimes the foams don't fit right. | 1 When the foams don't fit | - | Unless I drape the wires over the rubber cover where the CEP plugs into the helmet to get them out of the way. | 0 | |
| 0 | | 0 | - | When turning right | - | Left slip out in right head movement. |
| 0 | | 0 | _ | Hang up on nape strap and collar. | | When wires pull. |
| 0 | | 0 | - | Wires get caught on collar and nape strap. | - | Only when wires are caught. |
| 0 | | 0 | - | | - | A few times but only when they are very dirty. |
| 0 | | I The plug does not form shape as readily as the yellow foam earplugs. Hard to insert. | s 0 | | - | If not properly inserted it tends to come loose. |
| - | Sliding the helmet over the plugs. | • | 0 | | 0 | |
| 0 | | 0 | | Wires catch on goggles sometimes. | 0 | |
| 0 | | 0 | - | } | 0 | |
| - | Did not fit, fall out. | 1 | - | | - | |
| - | Foam does not expand fast enough and cord pulls earplug out. | 1 Little plastic tubes can scrape inner ear. | - | The wires pull on my earplugs when I turn my head | 0 | |
| 0 | | Occasionally the plastic insert extends beyond the foam and pokes me in the ear. | | Only when I have them stuck on something behind me. | 0 | |
| 0 | | 0 | - | Sometimes the wire catches and tugs on the earplugs. | 0 | |
| - | Hurt the ears with the probe going down the canal. | 0 | 0 | | | Because they hurt, I would leave them loose. |
| 0 | | 0 | - | Every once in a while if wires are twisted. | 0 | |
| • | Originally I was given a small and sometimes have a hard time with goggles aligning. | 0 | 0 | | 0 | |

| Q1 Unit location | Q1 ID Num | | Q14 Difficulty in fitting CEP | Q15 Disc | omfort inserting CEP | Q16 Wire: when | Q16 Wires pull on CEP when turning head | Q17 CEP durii | Q17 CEP move in/out of ear during flight |
|---------------------|-----------------------------------------|---|----------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|---------------------|-----------------------------------------------------------------------------------------|
| ø. | 2 | 0 | Ĭ | 0 | 1 | | Every time I turn to the left, my right earplug gets pulled on. | _ | Right ear plug does not fit properly, not known if it is my ear or the foam ollug |
| | 6 | - | Started off with standard length which caused discomfort in my ear canal because of length. Switched to short which eliminated the problem. | 0 | | _ | They hang up on shoulder hamess and upturned flight suit collar. | - | When the wires hang or pull. |
| | 4 | 0 | | 0 | | _ | | - | You must ensure a very good fit prior to flight to ensure they stay in. |
| | 2 | 0 | | 0 | 0 | • | | 0 | |
| | 9 | _ | | _ | 1 | _ | | _ | |
| | 7 | _ | | _ | 1 | _ | | | |
| | ∞ | 0 | | - | Just a slight discomfort | _ | They catch on the nape of my neck, especially when sweating. | 0 | |
| | 6 | 0 | | 0 | - | _ | They get caught on the flight suit collar, safety harness, ICS cord, NVG retention strap. | 0 | |
| | 10 | _ | The foam plugs are too mushy and start to expand very quickly. The housing hurts when it is pressed by earcups. | 0 | | | | - | Seldom |
| | ======================================= | 0 | | _ | Discomfort after 2 hours. | _ | | _ | Sometimes |
| | 12 | 0 | | - | Initially there was discomfort after flying 1 for 1 hour or more. | | Excess wire catches on clothing and other wires. | 0 | |
| | 13 | - | Very narrow ear canals - must trim the slim ones even slimmer - plus the foam spins off tot easily. | - | Inner tube too rigid - scrapes inner ear | | They catch on everything | 0 | |
| | 14 | 0 | | 0 | 0 | | | 0 | |
| • | 15 | 0 | | | 1 | _ | | 0 | |

| of ear | | s. As in #14 | | | | | | | long flights | The center core sometimes prohibits the sponge insert to compress small enough for proper fit. | | | | |
|------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|----|----------------------------------------|------------------------------------------------------------------------------------------------------|---|--------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------------------|------------------------------------------------------------------|----|--------------------------------------------------------|---------------------|
| Q17 CEP move in/out of ear during flight | | Due to my ears. As in #14 | | | See #14 | | | | Sometimes on long flights | The center core sometimes prohibits the sponge insert compress small enough for proper fit. | | | | |
| Q17 CEP durii | 0 | - | 0 | 0 | - | 0 | 0 | 0 | | | 0 | 0 | 0 | 0 |
| Q16 Wires pull on CEP when turning head | Usually occurs after 2 hours of flight. Wires hang up on my neck and when I turned my head - it pulls the plug out. | | | Sometimes when not installed properly. | Only if wire comes loose of Velcro, usually occurs on NVG flights with other wires Velcro to helmet. | | The wires catch on seat belts and other items. In the South with the humidity the wires stick to your neck and pull out when you turn your head. | Occasionally when wearing other cords around the neck (NVG cord, flashlight) | | | Turning my head hard to my left pull on the left side plug wire. | | The Velcro comes loose with NVG battery pack installed | |
| Q16 Wire | | 0 | 0 | - | - | - | - | - | 0 | 0 | - | 0 | 1 | 0 |
| Q15 Discomfort inserting CEP | | Same as #14 | | | Scraping of canal | | After prolonged wear the center tube irritates the ear canal. | | | | They are too big. | | The edges on the end are sharp | May be too large. |
| Q15 Disc | 0 | n 1 | 0 | 0 | - | 0 | - | 0 | 0 | 0 | - | 0 | - | - |
| Q14 Difficulty in fitting CEP | | Constantly jabbed ear when inserting them because my ear canals are irregularly shaped | | | Finding the right size plug and keeping it in the ear canal. | | | | | | | | | May need slim plugs |
| | 0 | - | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | - |
| Q1 ID Num | 91 | 11 | - | 7 | m | 4 | S | 9 | 7 | • | 6 | 10 | = | 12 |
| Q1 Unit location | ∞ | | ·6 | | | | | | | | | | | |

| Q1 Unit location | Num | Q1 Q14 ID Difficu Num | Q1 Q1 Q14 Unit location ID Difficulty in fitting CEP Num | Q15 Discor | Q15 Discomfort inserting CEP | Q16 Wires | Q16 Wires pull on CEP when turning head | Q17 CEP r during | Q17 CEP move in/out of ear during flight |
|-----------------------|---------|-----------------------------|----------------------------------------------------------|----------------|---------------------------------|--------------|---------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------------------------------------------------------------|
| .6 | 13 | 0 | | 0 | | - | | - | When it gets caught on flight vest and there is head movement. |
| | 14 | 0 | | 0 | | 1 | | _ | |
| | 15 | 0 | | 0 | | - | Wires tangle in/on other wires and attachments. | 0 | |
| Ş | 16 | 1 | Difficult to keep them in while putting helmet on. | - | With standard size | 0 | | - | After 30 minutes -1 hour when flying in hot and humid environments (86+ degrees. Sweating caused the CEP to slip out during flight. |
| .0. | - | 0 | | 0 | | - | Sometimes I think it is when the wires are more toward the cheek than the chin. | 0 . | |
| Overall Total N = 152 | N = 152 | Yes = N = | 35 117 0 | Yes = N = NR = | = 50 = 100 | Yes = NR = R | Yes = 114 N = 38 NR = 0 | Yes = N = NR = = | 70 81 |

| Q1 Unit location | P U S | Q1 Q18 ID SHORT Num wire | LONG | Q19 Night flight problems | Q20 Connector interference | Q21 Connector location | Q22 Clean or | 20 | Q24 Wax |
|---------------------|-------|--------------------------------|------------|-------------------------------------------------------------------------------------------------|--------------------------------------------------------|----------------------------------|-----------------------------------|------------------------------------------------------------|------------|
| | | | | | | | cdin ogunio | process | dn-puno |
| : | | Just right | Just right | 0 | 0 | - | 20 hours | Wash in flight suit | c |
| | 7 | Just right | Just right | 0 | 1 Sometimes it will interfere with NVG power cord | - | 25-30 hours | Wash them with my flight suit | . 0 |
| | ю | Just right | Just right | 0 | Power cord to NVG battery pack | - | Insufficient #s to know | N/A | 0 |
| | 4 | Just right | Too long | 0 | 0 | - | Haven't yet | | 0 |
| | S | Just right | Too long | 0 | 0 | 0 I don't know of another place. | | rubbed between hands with soap. | ds 1 |
| | 9 | | | 0 | 1 Sometimes. See #16 | 1 | Cleaned about 25 hours | wash in hands with soap | 0 |
| | 7 | Too short | Too long | Same as above | 0 | | 5 hours | Wash in flight suit | - |
| • | •• | Just right | Just right | 0 | Earcups when putting helmet on | | Haven't | Haven't | 0 |
| | 6 | Just right | Just right | 0 | 1 Sometimes. See #16 | _ | When they get dirty | Put them in my flight suit pocket during laundering. | t 0 |
| | 9 | | | Wire gets hung up and hard to find and secure. | 1 See above | _ | N/A, only lasted three flights | N/A | 0 |
| | | | Too long | 0 | 1 | 1 | Once every three months | Washed with uniforms | 0 su |
| | | Just right | Just right | 0 | 0 | - | | Washed in flight suit pocket | 0 |
| | 13 | Just right | Just right | 1 Sometimes the CEP wire gets caught on all of the other wires hooked to the back of the helmet | 1 See above | - | Whenever they appear dirty | Left them in my flight suit pocket and washed it | = |
| | 41 | Just right | Just right | 0 | 1 Sometimes on your clothes | _ | 10 hours | In the pocket of ABDUs in washing machine | - |
| | 15 | Just right | Just right | 0 | 1 As described in #16 | | Bi-weekly | In flight suit in washing machine | 0 |

| Q1 Unit location | Q1 UN Num | Q18 SHORT wire | LONG | Q19 Nigh prob | Q19 Night flight problems | Q20 Con | nector ference | Q21 Connector location convenient | on | Q22 Clean or change tips | Q23 Cleaning process | Q24 Wax build-up |
|---------------------|-----------------|----------------------|------------|---------------------|----------------------------------------------------------------------------------------|------------|------------------------------------------------|----------------------------------------------------|-------------------|------------------------------------|---------------------------------|------------------------|
| _ | 16 | Just right | Just right | 1 | Sometimes when turning head one of the CEPs would pull - wire adjustment fixed problem | 0 | | - | | Each week | In sleeve pocket normal wash | 0 |
| | 11 | Too short | Too short | 0 | | - | Helmet wire, seat back | 0 In earcup, or separate volume controls on helmet | eparate ols on | Didn't work long enough | | - |
| | 81 | Just right | Just right | 0 | | 0 | | | | 40-50 hours | Didn't | 0 |
| | 16 | Just right | Just right | - | Same as above. See Q #15-17 | - | NVG strap catches it and pulls CEP from ear | - | | 10 hours | In wash | 0 |
| | 70 | Too long | Too long | - | NVG neck cord. See #16 | _ | NVGs | 1 | | I didn't | I don't | 0 |
| | 21 | Just right | Too long | 0 | | 0 | | 1 | | 50 hours | Mild detergent | 0 |
| | 22 | Just right | Just right | 0 | | 0 | | 1 | | 10 hours | Soap and water | 0 |
| | 23 | | Just right | 0 | | 0 | | Move on the side | ide | | | 0 |
| 2. | | | | | | | | | | | | |
| | - | Too short | Too short | - | Getting tangled with the NVG battery pack. | 0 | | - | | 3 months/100 hours | Just get new ones. | 0 |
| | 7 | Just right | Just right | 0 | | 0 | | 1 | | 25 hours | | 0 |
| | ۳ | Just right | Too long | 0 | | - | It catches on intercom wire and seat belt. | - | | 50 hours then replace | Washed in washing machine. | 0 |
| | 4 | Just right | Just right | - | Velcro rubs on neck. Get rid of Velcro. | - | | - | | 30 days garrison, 10 days field | N/A | 0 |
| | 2 | Too short | Too long | - | See #16 | - | See #16 | 1 | | Every month | Washed with uniform | 0 u |
| | 9 | Just right | Just right | 0 | | - | Catches on survival vest and pulls out of ears | _ | | 50 hours | Wash in flight suit | 1 |
| | 7 | Just right | Just right | - | As stated in #16 | 0 | Except as above | 1 | | 20 hours | Wash in pocket of flight suit | - |

| Q1 Unit location | Q1 ID Num | Q18 SHORT wire | LONG | Q19 Night flight problems | | Q20 Connector interference | Q21 Connector location convenient | Q22 Clean or change tips | Q23 Q Cleaning W process bu | Q24 Wax build-up |
|---------------------|-----------------|----------------------|------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------|-----------------------------------------|------------------------|
| 2. | ∞ | Too short | Too short | 0 | | 0 | 1 | After each flight | Wash in flight suit | - |
| | 6 | Just right | Just right | 0 | | . 0 | - | 10-20 | pocket Soapy water | 0 |
| | 10 | Just right | Too long | 1 See #16 | | Wires catch on nape strap buckle | - | 60-70 hours | Was told not to clean - get new ones | |
| | = | Just right | Just right | 0 | | 1 See #16 | | Do not have any to replace. Need more foam inserts | Warm water | - |
| | 12 | Just right | Just right | 0 | | 1 ICS cable has at times pulled from my ear canal | - | 30 | Just changed them out | 0 |
| | 13 | Too short | Too long | 0 | | Long wire gets caught on vest | 1 | 20 | Wash in flight suit pocket | 0 |
| | 4 | Just right | Too long | 0 | | Vest - pinches between vest and neck | 1 | Not cleaned yet | Still work. Don't break up a good thing | 0 |
| | 15 | Just right | Too long | 0 | | 0 Very infrequently | - | 30 hours | Hand wash in soap and water | 0 |
| | 16 | Too short | Too short | 0 | | NVG flight on battery pack wires | 1 | 10 | Washed in flight suit | 0 |
| | 11 | Just right | Just right | 1 Speaker and out | Speaker cutting in and out | 1 Shirt/goggle | - | 10-15 | Wash with flight suit or exchanged | |
| | 81 | Just right | Too short | O Wires would attached to be of helmet up point at the bottom of the covers (cups) | Wires would be uttached to bottom of helmet up to the point at the oottom of the ear coetom of the car | 1 Anything behind neck | (). - | Not many | Got new ones or washed with uniform | |
| | | | | 0 | | 0 | 0 It should be inside, under CEP, to minimize. Wires are always in the way | Once a week | soap and water | 0 |

| Q1 Unit location | Q1 ID Num | Q18 SHORT wire | LONG | Q19 Night flight problems | | Q20 Connector interference | Q21 Connector location convenient | Q22 Clean or change tips | | Q23 Cleaning process | Q24 Wax build-up |
|---------------------|-----------------|----------------------|------------|---------------------------------------------------------------|--------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------------------------------|--------------------------------|----------|---------------------------------------------------------|------------------------|
| 2. | 20 | Just right | Just right | 1 Can s caugh in the tangk helme | Can sometimes get saught on things in the aircraft or angled in other relmet mounted | 1 Can sometimes get caught on other equipment but has little effect on job performance to the negative | | 130 hours | | Didn't | . |
| ຕໍ | - | Too short | Just right | 1 Gets 1 NVG | Gets tangled with NVG cord | _ | _ | 25-30 | | Soap and water | 0 |
| | 2 | Too short | Just right | 1 Stem earplt | Stem broke- earplug stuck in | 1 50% vest | - | Every time wash fligtsuit | | Leave in flight suit pocket and clean in washer | 0 |
| | m | Too short | Just right | 0 | | 0 | _ | 20-30 | | Leave them in left shoulder pocket during washing | 0 |
| | 4 | Too short | Too short | 1 See #16 | | 1 Sec 16,19 | | Every two weeks or as needed | weeks or | Wash them | 0 |
| | S | Too short | Too long | 0 | | 1 Wire length too short or long and limited space in a/c | 0 L or R side of helmet | met 50 | | Hot water | - |
| | 9 | Just right | Just right | 1 See q | See question 16 | 0 | | Monthly | | Put in pocket when washing flight suit | 0 |
| | ٢ | Just Right | Just right | I Install in the helme occas prove | installing the CEP in the back of the helmet at night occasionally proves difficult | 0 | - | occasionally | | Placed in pocket of flight suit and laundered. | - |
| | ∞ . | Just right | Just right | 1 With the applicatic ODAs an that is too items atta our helm | on o f d NVGs o many iched to | 1 See 19 | 0 | Never did | | Didn't | 0 |
| | 6 . | Just Right | Just Right | 0 | | 0 | | 100 | | Wash/laundered | |
| | 9 = | Too long | Too long | 00 | | 0 0 | 1 1 | unknown 150 | | Wash with flight suit Replaced | 0 0 |
| | |) |) | | | , | • | | | |) |

| Q1 Unit location | Q1 Num | Q1 Q18 ID SHORT Num wire | LONG | Q19 Night flight problems | Q20 Connector interference | Q21 Connector location convenient | Q22 Clean or change tips | Q23 Cleaning process | Q24 Wax build-up | |
|---------------------|-----------|--------------------------------|-----------------------------|------------------------------------------------------------------------------------------------|-------------------------------------------------|--------------------------------------------------------------------------|--------------------------------|-----------------------------------------|------------------------|---|
| 3. | 12 | Just right | Just right | 1 Too many wires | - | | 9 | Wached in Bight suit | | |
| | ; | | , | | | • | • | pocket | 1 | |
| | 13 | Too short | Just right | 0 | 0 | 1 | 15 | Washing machine - in pocket of clothes | - in 1 | |
| | 14 | Too short | Too short | 0 | 0 | | 150 | Replaced | 0 | _ |
| | 15 | Too long | Too long | 0 | 1 ICS cord and vest | 1 | | Stopped using | | |
| | 91 | | | 0 | 0 | 0 | Did not wear long enough | | 0 | |
| 4. | 17. | Just right | Just right | 0 | 1 | 1 | | | 0 | _ |
| : | _ | Too short | | 0 | 1 Vest or goggle mount | _ | | Wash | | |
| | 7 | Too short | Too short | 0 | 1 Collar | | Every month or so. | Washed them in my flight suit. | y 0 | _ |
| | er. | Too short | Just right | 0 | 1 Only to the extent of inconvenience. | O The side, if not, just make it easier to plug in with gloved hand. | l month in | Left in flight suit while laundering | while 0 | |
| | 4 | Too short | Too short | 1 Same as day | | 0 | Each time | Water | 0 | _ |
| | v. | Just right | Just right | 1 You have to make sure you have all your ALSE gear on before you put on your CEP. | 1 Too many wires in the cockpit, i.e. NVG commo | - | 5 hours | Put in flight suit then washed it. | en 1 | |
| | 9 | I don't know. | I don't know. I don't know. | 0 | 1 Seatbelt | 0 | 30-40 hours | In my hand with soap. | oap. 0 | |
| | ۲ . | Too short | Just right | 0 | 0 | 0 It's hard to get plugged in. I don't think moving it would help. | Haven't cleaned | | • . | _ |
| | ∞ | | | 0 | 1 Not too bad | - | | | 0 | _ |
| | 6 | Too short | Too short | 1 Fall out | 1 NVG neck piece | 0 Bigger and easier connection | 5 hours | wash | - | |

| pt Init location | Q1 Num | Q18 SHORT wire | LONG | Q19 Night flight problems | Q20 Connector interference | Q21 Conn conve | Q21 Connector location convenient | Q22 Clean or change tips | Q23 Cleaning process | Q24 Wax build-up | dr |
|---------------------|-----------|-------------------------------------------------------|----------------------------------------------------------------------------------|---------------------------------------------------------------|--------------------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------|----------------------------------------|-------------------------------------------------------------|------------------------|----|
| | - | Too short | Too short | 0 | Wire tends to lodge under shoulder restraint and pull loose. | ge 1 straint | | N/A | N/A | | |
| | 7 | | | 0 | 0 | - | | 40 | Soap and water. | | 0 |
| | 9 | Just right | Just right | 0 | 0 | 1 | | Clean weekly | By hand with soap and water. | | 0 |
| | 4 | Too short | Just right | 0 | 0 | ered | | About 10 | Left them in flight suit pocket and washed flight suit. | suit | _ |
| | S | Just right | Just right | 0 | 1 See #16 | - | | Have not cleaned them yet. | | | 0 |
| | 9 | Too short | Too short | I Going thru the process of plugging in the CEP to the helmet | 1 See#16 ging te | 0 | On the back with finger guides to the CEP hole, thus requiring you not to look at where the plug in is. | 9 29 | Warm soapy water then rinsed them in hand under sink. | | 0 |
| | 7 | Just right | | Sometimes it tangles around the aircraft battery. | the 0 | 1 | | 50 hours | Water | | 0 |
| | • | Just right | Just right | 0 | 0 | 1 | | I'll never tell. | In flight suit and normal wash cycle. | | 0 |
| | 6 | Just right | | 0 | 1 Refer to #16. | 0 | Hard to put in with helmet on | Haven't yet. | N/A | | 0 |
| | 10 | Too short | Just right | 0 | 0 | - | | Didn't change them yet. | Washed in machine in pocket of flight suit. | | 0 |
| | Ξ | Didn't know they had different wire lengths. | Didn't know Didn't know they had they had different wire different wire lengths. | 0 9 | 0 | - | | So far - never. | N/A | | 0 |
| | 13 | Just right | Too long | 0 | 0 | - | | Clean them every 4 flights (10 hours). | Soap and water | | 0 |
| | 13 | Too short | Just right | 0 | 0 | 0 | On the side | Haven't had them long enough | | | |

| 5. 14 Just right Just right 1 Catches on shoulder 1 6. 1 Too short Just right 1 Initially hard to get of because it of b | Q19 Q20 Night flight Connector problems interference | Q21 Connector location convenient | Q22 on Clean or change tips | Q23 Q Cleaning W process by | Q24 Wax build-up |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|-----------------------------------|--------------------------------------------------------------------|-------------------------------------------------------------|------------------------|
| 15 Too short Just right 0 1 Catches on shoulder 1 Los short Just right 0 0 0 0 0 0 | 0 | 1 | Have not cleaned | | |
| 15 Too short Just right 0 1 Catches on shoulder 1 | | | yet | | > |
| 1 Too short Just right 1 Initially hard to get 0 0 0 | 1 | on shoulder 1 straps. | Not done yet. | Not done yet. | 0 |
| 1 Too short Just right I Initially hard to get 0 used to because I never wore earplugs prior to the CEP modification. 2 Just right Just right 0 0 0 1 See #16 5 Just right Just right 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | 0 | | | | 0 |
| 2 Just right Just right 0 0 1 3 Just right Just right 0 0 1 5 Just right 0 0 0 1 6 Too short Just right 0 0 1 Tends to get caught 0 0 1 8 Too long Too long 0 1 Long wire would catch 0 1 9 Just right Too long 0 1 Catches on vest. 0 1 Too short Too long 0 1 Catches on vest. 0 2 Just right Just right Just right 0 0 1 2 Just right Just right 0 0 0 1 | es | | Once the ECU comes on Monthly line, what are we going to do? | Washed them IAW briefing instructions (flight suit pocket). | 0 |
| 3 Just right Just right 0 0 1 4 Too short Just right 0 0 0 0 6 Too short Just right 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | 0 | Never | I don't they're orest | - |
| 4 Too short Just right 0 0 0 6 Too short Just right 0 0 1 7 0 0 0 1 8 Too long Too long 0 1 Tends to get caught 0 9 Just right Too long 0 1 Long wire would catch 1 10 Too short Too long 0 1 Catches on vest. 0 1 Too long 0 1 Catches on vest. 0 2 Just right Just right Just right Just right 0 0 2 Just right Just right 0 0 0 1 | | 1 | Haven't vet | Haven't vet | · - |
| 5 Just right Just right 0 0 0 7 0 0 0 1 8 Too long 0 1 Tends to get caught 0 9 Just right Too long 0 1 Long wire would catch 1 10 Too short Too long 0 1 Catches on vest. 0 1 A Just right Just | | - | 10-20 | In ABDU flight suit pocket in washing machine. | 0 |
| 6 Too short Just right 0 1 See #16 1 8 Too long Too long 0 1 Tends to get caught 0 9 Just right Too long 0 1 Long wire would catch 1 on flight vest. 10 Too short Too long 0 1 Catches on vest. 0 1 | | 0 | NA | Wash and drver | c |
| 7 0 0 0 1 | 1 | 1 | 30 | Wash with flight suit. | 0 |
| S Too long 100 long 1 Tends to get caught 0 | 0 | 1 | 10 hours | Water | 0 |
| 9 Just right Too long 0 1 Long wire would catch 1 on flight vest. 10 Too short Too long 0 1 Catches on vest. 0 1 | - | get caught 0 | | | 0 |
| 10 Too short Too long 0 1 Catches on vest. 0 1 0 1 Especially when wearing NVGs 1 2 Just right Just right 0 0 3 Too long 0 1 | 1 | ire would catch 1 I vest. | Washed with flight suit. | Regular washing. | 0 |
| 1 0 1 2 Just right Just right 0 0 3 Too long 0 0 | | | Don't wear it. | N/A | 0 |
| Just right Just right 0 Too long 0 | 1 | ly when I NVGs | haven't | replaced them | 0 |
| Too long 0 | | | 100 | Soan and water | c |
| | | end | 50 | Tried to wipe them off with a damp cloth | |

| Q24 Wax build-up | • | 0 | | | 0 | _ | 0 | _ | - | 0 | 0 | 0 | _ |
|-----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|--------------------|-----------------------------------------------|------------|--------------|-----------------|------------|-----------------------------|------------------------------|------------------------------------------------------------|---------------------------------------------------------|------------|
| Q23 C Cleaning V process b | Soapy water and rub between fingers | | Washed with flight | Placed in flight suit pocket and laundered | I don't | Wash | | Replaced | Soapy water | Never cleaned, just replaced | Replaced | Didn't | Replaced |
| Q22 Clean or change tips | s 10 | | 100 | When dirty | 75 | Periodically | No replacements | | Never - too hard to replace | 09 | 10 | Kept breaking, didn't get a chance to clean them. | 100 |
| Q21 Connector location convenient | 1 Perhaps two short wires 10 located on the helmet nearest the ears. The best solution is no external contraption. | s eed | _ | 1 | 1 | 1 | _ | | _ | - | 1 | gant | |
| nector ference | Sec #16 | As explained | | Seatbelt | | Occasionally | | | See #17 | | We wear ANVIS power cords and flotation, it tends to snag. | | |
| t flight lems | There are already too many wires coming off your head, There is the oversized ICS cord, 550 cord for NVG, A/C power for NVGs, ODA cord, and the CEP cord. I'd hate to think what flying in an NBC environment would be. | From time to time 1 catches on NVG power supply cable system. | 1 | 1 | 0 | 1 | 0 | 0 | - | | - | 0 | 0 |
| Q19 Nigh prob | - | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| LONG | | Too short | too long | Too long | Just right | Too long | Too long | Too long | Too long | Too long | Too long | Just right | Just right |
| Q18 SHORT wire | | Too short | Just right | Just right | Just right | Just right | Just right | Just right | Just right | Just right | Just right | Just right | Just right |
| Num Num | 4 | ٠ د | 9 | 7 | 00 | - | | | | 13 | 4 | 15 | 16 |
| Q1 Unit location | 7. | | | | | | | | | | | | |

| 10 | 10 | 018 | | Q19 | | Q20 | Q21 | Q22 | Q23 | 024 | |
|---------------|------|---------------|------------|---------------|------------------------------------------------------------------------------------------|------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------|------------------------------------------------|-----------------|--|
| Unit location | Num | SHORT wire | LONG | Nigh probl | t flight ems | Connector interference | Connector location convenient | Clean or change tips | Cleaning process | Wax build-up | |
| 7. | | | | | | | | | | | |
| | 17 | | | 0 | | 0 | 0 | 5 | Water | 0 | |
| | 18 | | Too long | - | - | - | 0 Inside | 10 | File 13 | | |
| | 19 | Just right | Too long | 0 | | 1 | | | | - | |
| | 20 | Just right | Just right | 0 | | 0 | | 10-100 depending on color | When washing flight suit | 0 | |
| | 21 | Just right | Just right | 0 | | 1 Sometimes | - | 75 | Replaced | - | |
| | . 22 | Just right | Too long | - | Same as above | They get hung on seatbelts behind my head. | O Try doing it at night while on a real world mission with a 15 minute launch time. | 25 ite | Soap and water | 0 | |
| ~ | 23 | Just right | Just right | 0 | | 0 | 1 | 15 | With flight suit in pocket. | - | |
| • | - | Just right | Too long | 0 | | | 1 | 50 hours (1 month) | Washed in flight suit pocket with foam | - | |
| | 7 | Just right | Just right | 0 | | 1 We have other wires strapped to our helmet, it tangles up. | - | Once a week | In my flight suits in the wash and air dry. | he 1 | |
| | m | Just right | Too long | - | Sometimes pulled by NVG power cord and ODA cable. | 1 See #16 and #19 | Inside helmet to eliminate exposed wires | 50 s | Washed in flight suit pocket | 0 | |
| | 4 | Too short | Too short | | CEP wire entangles in ICS wire, ODA, NVG power supply. I'm a flying octopus. | 1 Sometimes catches and restricts head movement. | - | 20 hours | Soap and water | qual | |
| | ٠, | Just right | Just right | 0 | | . 0 | 1 | Have not changed them | Have not cleaned them | 0 m | |
| | 9 | | | 1 | | - | 0 | Never | d/n/a | | |
| | 7 | | Too long | 0 | I did not try it. | 1 | | | | 0 | |
| | 00 | Too short | Too short | | | 1 In the OH-58D we have several other cords to contend with. | | 100 | In my flight suit in the laundry | O . | |
| | | | | | | | | | | | |

| Q1 Unit location | Q1 ID Num | Q18 SHORT wire | LONG | Q19 Night flight problems | Q20 Connector interference | Q21 Connector location convenient | Q22 Clean or change tips | Q23 Cleaning V | Q24 Wax build-up |
|---------------------|-----------------|-----------------------------|------------|--------------------------------------------------------|--------------------------------------------------------------------------|-----------------------------------------------|------------------------------------|-----------------------------------------------|------------------------|
| ં | 6 | Just right | Just right | 0 | 1 See #16 | 1 | 45 | Replace the extremely | - |
| | 10 | Just right | Just right | 0 | . 0 | 1 | 2 | Washed inside flight suit pocket | 0 |
| | .= | Just right | Just right | 0 | 0 | 1 | 100 | Swapped out | 0 |
| | 13 | Too long | Too long | 1 See #16 | 1 Catches on NVG/ODA cord and ICS cord | 1 | 10 | Laundered in flight | 0 |
| | 13 | Too short | Too short | 0 | | 0 Individual wire and connector for each ear. | 1 week needed replacement | Soap and water | - |
| | 14 | Too short | Too short | 0 | 0 | _ | 25 | Threw them away | 0 |
| | 15 | Too short | Just right | | 1 The OH-58D has three other wires attached to the head/helmet and ANVIS | _ | I didn't | | 0 |
| | 91 | Just right | Just right | 1 Plug pulls out. See #16. | 1 Occasionally it will hang up on other helmet parts | 1 | 100 hours | I didn't. I replaced them. | 0 |
| 6 | 11 | Just right | | 0 | 0 | 0 | 10 hours | Washed in flight suit | 0 |
| ζ. | _ | Just right | Just right | 0 | 0 | - | 25 hours | Wash in pocket of flight suit | 0 |
| | 7 | Just right | Just right | 0 | 1 NVG neck cord/chin strap | | 50 hours, need more tips | Leave in pocket of flight suit during wash | • |
| | m | | | 1 See #16 | 0 | | 60 or 80 hours (clean at 20-40) | Soap and water | - |
| | 4 | Just right | Too long | 0 | 1 Long wire on vest sometimes. | 1 | Every 2-3 flights | Wash in arm pocket of flight suit. | |
| | 'n | Just right | Too long | 1 Extra wires are getting caught on items in aircraft. | 1 They catch on seatbelts, ICS cords and stick to you. | - | | Wash with flight suit | 0 |
| | 9 | Just right | Just right | 1 See #16 | 0 | 1 | 20 | Wash in flight suit | 0 |
| | 7 | Too short | Too short | 0 | 0 | 1 | 100 hours | Flight suit pocket | - |

| Q1 Unit location | Q1 ID Num | Q18 SHORT wire | LONG | Q19 Night flight problems | Q20 Connector Cinterference | Q21 Connector location convenient | Q22 Clean or change tips | Q23 Cleaning process | Q24 Wax build-up | ۾ |
|-----------------------|-----------------|---------------------------|-----------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------|--------------------------------|---------------------------------------------|------------------------|----|
| 6 | œ | Just right | | 0 | 0 | 1 | 10 | Inside flight suit pocket during laundry | rī 0 | |
| | 9 10 | Too short Too short | Just right Just right | 0 0 | 0 | 1 | 10 | Clean them? Washed in flight suit | it 0 | |
| | = | Just right | Just right | 1 See #16 | 0 | 0 It would be better if all I haven't connectors were in one plug | I haven't | See above | 0 | |
| | 12 | Just right Too short | Just right Just right | 0 | 0 1 Flight vest | - | Haven't yet | Haven't yet | 0 | |
| | 14 | Just right | Too long | 0 | 0 | - | Clean once a week | Wash with flight suit | | |
| | 15 | | | 0 | 1 Other attachment - NVG cord | 0 Somewhere more convenient. | Every flight | Washed in flight suit | | |
| | 16 | Too short | Just right | and wires to hook up and keep from getting tangled I.e. CEP, NVG battery pack, NVG lanyard, extension cable for battery pack, ICS cord, ODA cord! | | | | Flight suit pocket in wash | 0 | |
| 10. | - | Just right | Just right | . 0 | | | 100, I'm lazy. | Flight suit pocket in washer | | |
| Overall Total N = 152 | N= 152 | Short-Just Long-Just r | Short-Just right 134 Long-Just right = 132 | Yes = 40 N = 109 NR = 3 | Yes = 78 $N = 72$ $NR = 2$ | Yes = 118 $N = 28$ $NR = 6$ | | | Yes = N = NR = | 37 |

| Q1 Unit location | Q1 UN Num | Q25 Canal discomfort | Rate disco | mfort | Q26 Exte | Q26 External ear discomfort | Q27 CEP | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|---------------------|-----------------|-----------------------------------|---------------|------------------------------|-------------|------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------|-----------------------------------|----------------------------------------|
| Τ. | 1 | 1 | 1 | | 0 | | 1 | When CEP comes in contact | 2 hours | |
| | 7 | _ | 1 | If inserted too far | 0 | | 0 | | 2-3 hours | - |
| | ю | 0 | | | 0 | | 0 | | | 4 |
| | 4 | 0 | | | 0 | | 0 | | | |
| | \$ | 1 | | | 0 | | 0 | | 4+ hours | 4 |
| | 9 | - | - | | - | Only if wire runs across ear and earcup - easy to fix. | 0 | | 2 1/2 hours | 5 0 |
| | 7 | 1 | 7 | | 0 | | 0 | | 2 hours | 4 |
| | ∞ | •• | 7 | | 0 | | 0 | | 2 hours | S |
| | 6 | | 1 1 | Itching | 0 | | 0 | | | 4 |
| | 10 | | | | - S | See #15 | _ | Ears hurt | 1/2 hour | æ |
| | 11 | 0 | | | 0 | | 0 | | | 4 |
| | 12 | 7 | - | | 0 | | 0 | | 2 hours | 7 |
| | 13 | - | 2 1 | If they start to come out | - S- G- D | Sometimes the wire coming out from under the earcup causes pain behind my ear. | 0 | l hour | | |
| | 14 | 1 | 2 | After 2 hours | 0 | | 0 | | 2 hours | 9 |
| | 15 | 1 | 7 | | 0 | | 0 | . 1/2 hour | | 4 |
| | 16 | 0 | | | 0 | | 0 | | 4 hours | 4 |
| | 17 | - | | Definitely | 0 | | 0 | | 2 hours | 4 |
| | 18 | _ | 7 | | | It just seems the black portion's (inner cylinder (not the part that the foam covers) irritates the outer portion of my ear canals | 0 | | 1/2 hour | ю |
| | 19 | - | - | Both itching and pain | _ | | | In ear canal | 3 hours | 4 |
| | 20 | 0 | | | 0 | | 0 | | | |
| | 21 | - | 7 | | 0 | | 0 | | 3 hours | 3 |
| | 22 | 0 | | | 0 | | 0 | | | ς. |

| 7 | 5 | 360 | |) i | | | | |
|---------------|----------|---------------------|-----------------------------------------------|--------------------------------------------------------------------------------------------|----------|----------------------|-----------------------------------|----------------------------------|
| Unit location | N G S | Canal discomfort | Rate discomfort | Q26 External ear discomfort | | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
| - | 23 | 0 | | 0 | o | | | |
| 2. | | | | | , | | | t |
| | - | 0 | | . 0 | 0 | | 4 hours | 4 |
| | 7 | 0 | | . 0 | 0 | | | |
| | 3 | 1 | 1 Itching | 0 | 0 | | 1 hour | • |
| | 4 | 0 | | . 0 | 0 | | | , |
| | S | _ | 1 On long flights | 0 | 0 | | 2 hours | . 4 |
| | | | uncomfortable. | | | | 0 | |
| | 9 | - | . 2 | 0 | 0 | | 2 1/2-3 hours | 4 |
| | 7 | 0 | | 0 | 0 | | | 4 |
| | ∞ | 1 | 3 | 0 | 0 | | 1 1/2 hours | 2 |
| | 6 | 0 | | 0 | 0 | | | 4 |
| | 10 | 0 | | Barrel of external earplug pressed against outside ear due to pressure from earcup | pressure | Sce #26 | 2.5 hours | · m |
| | 11 | 0 | | | 0 | | | , |
| | 12 | 0 | | 0 | 0 | | | 4 |
| | 13 | 1 | | 0 | 0 | | 1/2 hour | 2 |
| | 14 | 0 | | 1 Cord - at times pinches between earcup if not positioned correctly | etween 0 | After 2.5 hours | 4 | ; +t |
| | 15 | - | Sometimes on long flights | 0 | 0 | 2 hours | 4 | |
| | 16 | 0 | | 0 | 0 | | | 4 |
| | 17 | 0 | | 0 | 0 | | 3.5 hours | 4 |
| | 28 | | | 0 | 0 | | 1 hour | 4 |
| | 19 | _ | 2 | 1 Too big | 0 | | Less than .5 hour | 2 |

| l nit location | Q1 ID Num | Q25 Canal discomfort | Rate discomfort | Q26 External ear discomfort | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|-------------------|-----------------|-----------------------------------|--------------------|------------------------------------------------------------------------------------------------------------------------|----------------------|-----------------------------------|----------------------------------------|
| 2. | 20 | - | 2 | 1 On long missions or several flights 0 over short period of time CEP will rest against outer ear and cause discomfort | 0 5 | 1 hour | |
| 3. | - | • | ÷ | | | | |
| | 7 | - 0 | Itch | 0 0 | 0 0 | 1/2 | ۲ 4 |
| | ю | 0 | | 0 | 0 | | + 4 |
| | 4 | 0 | | 0 | 0 | | |
| | ~ | 0 | | 0 | 0 | 4 | 7 |
| | 9 | 0 | | 0 | 0 | 1.5 | ٠ ٧٠ |
| | 7 | 0 | | . 0 | 0 | | 4 |
| | ∞ | 0 | | 0 | 0 | | 4 |
| | 6 | _ | - | 0 | 0 | | 4 |
| | 0 | 0 | | . 0 | 0 | | 4 |
| | Ξ | - | - | 0 | 0 | 2 | 4 |
| | 12 | 0 | | 0 | 0 | | 9 |
| | 13 | | | 0 | 0 | 7 | · v r |
| | 14 | - | - | 0 | 0 | | m |
| | 15 | - | 2 | 0 | 0 | 1/2 hour | 4 |
| | 16 | - | 2 | 1 The metal part of the CEP presses into my ears | 0 | 1/2 hour | |
| | 17 | 1 | 2 | 0 | 0 | 1/2 hour | 4 |
| 4. | _ | **** | - | c | c | | • |
| | • | • | • | | | I/2 hour | 9 |
| | 7 | 0 | | 0 | 0 | | 40 |
| | m | | 2 Pain | 0 | | 1 hour | 7 |
| | 4 | - | 3 | 1 Hurt | . 0 | 1/2 hour | - |

| Q1 Unit location | Q Um Num | Q25 Canal discomfort | Rate discomfort | Q26 Exte | Q26 External ear discomfort | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|---------------------|----------------|-----------------------------------|--------------------|-------------|------------------------------------------------------------------|----------------------|-----------------------------|----------------------------------------|
| 4. | | | | | | | | |
| | 2 | 1 | 2 | 0 | | 0 | | 9 |
| | 9 | - | 2 | 0 | 0 Just canals. | 0 | 1/2-1 hour | " |
| | 7 | 0 | | 0 | | 0 | | , 4 |
| | ∞ | - | 1 | - | After 2-3 hours | 0 | 3 hours | |
| | 6 | ••• | 1 | 0 | | 0 | 3 hours | o ve |
| 5. | | | | | | | | > |
| | - | - | 1 | 0 | | 0 | 1 hour | 4 |
| | 2 | - | 1 | 0 | | 0 | | . 4 |
| | 3 | - | 2 Itching | 0 | | 0 | 1 hour | י מ |
| | 4 | - | 2 | 0 | | 0 | | י ע |
| | 2 | - | 2 | 0 | | | 1 hour | , , |
| | 9 | 0 | | 0 | | | | - (|
| | 7 | - | 2 | | See #12. | 0 | 10 hour | n 4 |
| | • | 0 | | 0 | | | IVE IIONI | n • |
| | 6 | 1 | 1 Pain | 0 | | | 10 hours | 4 - |
| | 10 | 0 | | 0 | | | 100m 7/1 | , |
| | Ξ | 0 | | 0 | | 0 | | 4 4 |
| | 12 | 0 | | 0 | | 0 | | 0 4 |
| | 13 | 0 | | 0 | In a way the hard part inside the | 0 | | 9 4 |
| | | | | | foam - if not rolled slowly the plastic may scratch on inserting | | | |
| | | | | | ure carping into the car. | | | |
| | 14 | 0 | | 0 | | 0 | | 80 |
| | 15 | 0 | | 0 | | 0 | | 9 |
| | 91 | | | | See #14 | 0 | 1/2 hour | , eo |

| Q1 Unit location | Q1 ID Num | Q25 Canal discomfort | Rate discor | mfort | Q26 Exte | mal ear discomfort | 027 CEP | hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|---------------------|-----------------|-----------------------------------|----------------|------------------------------------------------------------------------------------------------------------------------------------------|-------------|----------------------------------------------------------------|-------------------|----------------------------------------|-----------------------------------|----------------------------------------|
| . | | - | 7 | Initially moderately uncomfortable | 0 | | 0 | | 1/2 hour | 4 |
| | 7 | 0 | | | 0 | | 0 | | | |
| | 33 | - | - | | 0 | | 0 | | | 4 |
| | 4 | 0 | | | 0 | | 0 | | | . 4 |
| | \$ | 0 | | | 0 | | 0 | | | . 19 |
| | 9 | - | | | 0 | | - | | 1/2 hour | 4 |
| | 7 | 0 | | | 0 | | 0 | | | |
| | ∞ | 0 | | | _ | If wire lays on top of outer ear it tends to cause a hot spot. | _ | See previous. | 1 hour | 4 |
| | 6 | | 7 | After 3-4 hours. | 0 | | 0 | | 3 hours | 4 |
| | 10 | - | ю | | - | The wires are pressed into my ear from the earcup. | ••• | Where the earcups push it into my ear. | 1/2 hour | |
| 7. | | | | | | • | | | | |
| | - | - | 7 | | 0 | | _ | On my ear against the cushions | 1/2 hour | 4 |
| | 7 | - | - | | 0 | | 0 | | 1/2 hour then subsides | 4 |
| | 3 | 1 | - | | 0 | | 0 | | | 4 |
| | 4 | - | 7 | The part that protruded from my ear is in contact w/ carmuff and after an hour of flying it becomes painful enough to take the CEPs out. | - | See #25 | 0 | | 1 hour | 'n |
| | S | - | 7 | | 0 | • | 0 | | 1/2 hour | 7 |
| | 9 | 1 | - | | 0 | | 0 | | 1/2 hour | , 7 |
| | 7 | 0 | | | - | Edges feel sharp | 0 | | | |

| Q1 Unit location | Q1 UNum | Q25 Canal discomfort | | nfort | Q26 Exte | Q26 External ear discomfort | Q27 CEP | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|---------------------|------------|-----------------------------------|---|------------------------------------|-------------|----------------------------------------------------------------------------------------------|-------------------|-----------------------------|-----------------------------------|----------------------------------------|
| 7. | 00 | 0 | | | 0 | | o | | | , |
| | 6 | gund | _ | Only when I get the wrong size. | 0 | | 0 | | | - 4 |
| | 10 | 0 | | | 0 | | 0 | | | 4 |
| | = | 0 | | | 1 S | Size of speaker | 0 | | 1 hour | |
| | 12 | 0 | | | 0 | | 0 | | 1 hour | 7 |
| | 13 | 0 | | | 0 | | 0 | | | 7 |
| | 14 | 0 | | | 0 | | 0 | | | |
| | 15 | 0 | | | 0 | | 0 | | | |
| | 16 | 0 | | | 0 | | 0 | | | 4 |
| | 17 | 1 | - | Itchy | 0 | | 0 | | 1 hour | · • |
| | 18 | 1 | 2 | | _ | | - | | 1 hour | 4 |
| | 19 | 0 | | | 0 | | 0 | | | . 4 |
| | 20 | - | - | Sometimes | 0 | | | Occasionally | 3 hours | 7 |
| | 21 | 0 | | | | Sometimes just a mild hot spot from the black plastic portion pressing against the outer ear | | See #26 | 1.5 hours | 4 |
| | 22 | 1 | 2 | | | | 0 | | 1/2 hour | 4 |
| | 23 | 0 | | | 0 | | 0 | | | |
| ∞ | | | | | | | | | | • |
| | - | 0 | | | 0 | | 0 | | 1/2 hour | 9 |
| | 7 | 0 | | | 0 | | 0 | | 3 hours | . 9 |
| | 3 | - | 2 | Only with standard foam tip | 0 | | 0 | | 1 hour | 9 |
| | 4 | _ | 2 | | 0 | | 0 | | 1 hour | s |
| | S | - | 7 | | 0 | | 0 | | 1/2 hour | e |
| | 9 | - | 2 | | 0 | | 0 | | 1/2 hour | _ |
| | 7 | - | 3 | | - | | 0 | | Less than 1/2 | _ |

| Q1 Unit location | Q1 ID Num | Q25 Canal discomfort | Rate discomfort | Q26 External ear discomfort | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|---------------------|-----------------|-----------------------------------|--------------------------------|--------------------------------------------------------------------------|----------------------|-----------------------------------|----------------------------------------|
| ·8 | ∞ | 1 | - | 0 | 0 | 1/2 hour | 7 |
| | 6 | - | 2 | 0 | 0 | | 4 |
| | 10 | 0 | | 1 The housing sometimes is pressed against the ear by the helmet earcup. | 0 pt | | 9 |
| | Ξ | - | 2 | 1 Soreness | l In ear canais | 2 hours | 4 |
| | 13 | - | ı | Initial discomfort was gone after 20 0 hours. | 20 0 | 1 hour | 9 |
| | 13 | _ | 2 | 1 Where the wire presses on earlobe. | be. 0 | 2 hours | 2 |
| | 14 | 0 | | 0 | 0 | | 7 |
| | 15 | - | 2 | 0 | 0 | 1/2 hour | 3 |
| | 16 | - | 2 After long flights (2.5 hrs) | 0 | 0 | 2 hours | 9 |
| | 17 | 1 | 1 Itching | 0 | 0 | 1/2 hour | 4 |
| 9. | , | , | | | | | |
| | - | 0 | | 0 | 0 | | 9 |
| | 7 | - | | 0 | 0 | 1/2 hour | 7 |
| | 3 | - | yeard | 0 | 0 | 1 hour | 4 |
| | 4 | 0 | | The metal connector on the outside of ear. | 0 | | 7 |
| | S | 1 | 2 After 3 hours | 0 | 0 | 2 1/2-3 hours | |
| | 9 | - | 1 Occasionally | 0 | 0 | 1 1/2 hours | 4 |
| | 7 | 0 | | 0 | 1 Flight with NVGs | 3 1/2 hours | 9 |
| | ∞ | 0 | | 0 | 0 | | 4 |
| | 6 | 0 | | 0 | 0 | | en |
| | 10 | 0 | | 0 | 0 | | S |
| | == | 0 | | 0 | 0 | | 9 |
| | 12 | 1 | - | 0 | 0 | 1 1/2 hours | 7 |
| | 13 | 0 | | 0 | 0 | | |

| Q1 Q25 Unit location ID Canal Rate Num discomfort discomfort | Q1 Num | Q25 Canal discom | fort | Rate discomfort | Q26 External ear discomfort | Q27 CEP hot spots | Q28 Onset of CEP discomfort | Q29 Rate overall fit and comfort |
|--------------------------------------------------------------|----------------|-------------------------------|------|--------------------|------------------------------------------------------------------------------------------------------|-------------------------------|-----------------------------|----------------------------------------|
| o | 14 15 16 | 0 1 0 | | 2 Itching | 0 0 1 Hard plastic when trying to keep CEP in the ear. | 0 0 | | 4 |
| 10. | - | 0 | | | Sometimes with the plastic part, however with the next generation there probably won't be a problem. | 0 | | ĸ |
| Overall Total N = 152 | N = 152 | Yes = 8 | -62 | Mean = 1.6 | Yes = 29 N = 123 NR = 0 | Yes = 13 N = 138 NR = 1 | | Mean = 4.6 NR = 10 |

| | | | | | I | | | | |
|--------------|-----------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|----------------------------|------------------------------------------------------|------------------------|---------------------------------------------------------------|--|
| ont location | Q1 ID Num | | Q30 Problem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | don/doff | Q33 Disco discor | Q33 Discomfort if forget to disconnect CEP from helmet | |
| | - | 0 | | . 0 | - | Next to impossible | - | | |
| | , | - | | | | arangadini aranga | | | |
| | 7 (| - | | | - | , | 0 | | |
| | ю | - | Care had to be taken when putting helmet on or it 0 pulled plug out | 0 1 | - | Cannot compress foam sufficiently to insert | _ | Caused plastic post to snap off | |
| | 4 | 0 | | 0 | 0 | | _ | Somewhat | |
| | S | - | | 0 | - | Much harder to feel the helmet adapter. | _ | Plastic tips sometimes scrape. | |
| | 9 | - | Extra care is required to not dislodge the CEP. | 0 | _ | They are small | 0 | | |
| | 7 | 0 | | | 0 | | _ | Due to the length of the cord, you rub them out of your ears. | |
| | • | - | Without spreading ear cups the CEPs normally hit the earcups. You must also take care not to pinch the wire while adjusting the helmet. | 0 | | You can't do it. | 0 | | |
| | 6 | - | Cannot put gloves on before donning helmet because I cannot put wire in helmet hole w/ gloves on. | 0 | - | Can't do it. | | What does doffing mean? | |
| | 10 | 1 | | 0 | - | | - | Plugs were pulled out of ear abruptly | |
| | 11 | - | Takes more time | 0 | - | Hard to put in the ear | 0 | | |
| | 12 | - | | 0 | 0 | | 0 | | |
| | 13 | - | Takes longer to get ready | 0 | 0 | | 0 | | |
| | 14 | 0 | | 0 | 0 | | 0 | | |
| · | 15 | - | You must be careful not to tug in the wires otherwise they pull the earplug out | | 0 | | 0 | | |
| | 91 | - | Must take special care not to pull the wires out while doffing. | 0 | | Hard to compress and seat the CEP into the ear | _ | Yanks the ### out of your ear | |
| | 11 | - | Remembering | 0 | 0 | | 0 | | |
| | 18 | - | The ear cups must be pulled over the black cylinders of as not to disturb them | 0 | 0 | | 0 | | |

| Q1 Unit location | QI Num Num | Q30 Problem donning/doffing helmet w/CEP | ffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | Q32 Problem don/doff w/gloves | Q33 Discomfort if forget to disconnect CEP from helmet | # |
|---------------------|------------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|---------------------------------------------------------|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|------------|
| • | | | | | | | | |
| | 19 | 0 | | 0 | c | | | |
| | 20 | 1 You have to be more helmet | You have to be more deliberate in donning the helmet | 0 | 0 | | | |
| | 21 | 1 Care is taken not to pare inserted in ear cuthe cars | Care is taken not to pull earplugs outthumbs are inserted in ear cups to pull the earcups over the ears | 0 | - | Hard to plug into helmet with gloves | 0 | |
| | 22 | 0 | | . 0 | • | 5 | | |
| 2 | 23 | 1 Must connect prior to putting on helmet | o putting on helmet | 0 | | Takes longer | | |
| .; | - | | | | | | | |
| | | wires and not pulling them out. | rou just rave to be more cautious about the wires and not pulling them out. | • | - | While compressing the CEP to put into the ears, it is difficult trying to feel if you are twisting the earplug off. As far as connecting to the helmet, it is more difficult making the connection with the helmet. | I The CEP would get yanked out of my ears. | d out of |
| | 7 | 0 | | 0 | c | | | |
| | ٣ | 1 | | 0 | | Harder to plug in | 0 | |
| | 4 | Careful placement of earcups ar prevent accidental dislodgment. | Careful placement of earcups around CEPs to prevent accidental dislodgment. | 0 | - | Cannot be done. | 0 | |
| | v o | | ups wider. | | | Locating where to plug the CEP into the helmet. | 1 Ripped them out of my ears. | ઝ ં |
| | 9 1 | | | 0 | 0 | I always insert w/o gloves on | . 0 | |
| | , | l Just hook-up/un-hook in sequence | k in sequence | 0 | pred | Sometimes hard to seat with connector with gloves. | 0 | |

| Q1 Unit location | QI Num Num | Q30 Prob | olem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem don/doff w/gloves | | Q33 Discomfort if forget to disconnect CEP from helmet |
|---------------------|------------------|-------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------|---------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|
| 2, | | | | | | | |
| | ∞ | | More crap to plug in! We already have too much 1 Yo crap attached to our heads. | You've apparently never tried this yourself. | 1 It hu | It hurt like hell | |
| | 6 | | Have to pull the earcups further apart so that they don't pull CEPs out | | 0 | | 0 |
| | 10 | | Expand earcups further/ extra time to put on 0 | | 1 Can' | Can't use gloves | 0 |
| | 11 | - | Must pull earcups out to avoid CEP pulling out 0 | | Neve | Never done it | 0 |
| | 12 | | It takes just a few more seconds to connect 0 | | 1 Canr HGL to in | Cannot feel the HGU-56 connector to insert the CEPs | 0 |
| | 13 | | Must spread helmet earcups apart further 0 | ٠ | 1 Getti some tries on. (| Getting proper fit sometimes takes 2-3 tries with gloves on. Gloves get CEP dirty quickly | 0 |
| | 41 | - | Having to undo shin strap to allow total expansion of ear cups in order not to pull CEP | | 1 No w the C with as r earpl conn helm find | No way can I place the CEP in the ear with glove on (same as regular earplugs). Plus connector into helmet is hard to find hole | 0 |
| | 15 | - | Must be careful not to pull them out when donning helmet | | l Hard back glow | Hard to plug into back of helmet with gloves on | 0 |
| | 91 | - | You must pull helmet wider apart to keep CEPs 0 from getting worked out by ear cups | | 0 | | 0 |
| | 17 | 0 | 0 | | | | 0 |
| | 8 | - | Only if CEP is caught on something and pulls out 1 On of the ear canal | Only when facing time constraints | 1 I was inser with | I was only able to insert foam tips without my gloves | 0 |
| | 19 | - | Very difficult process I Wi | Wires in the way and distracting pain | 1 Can' | Can't feel | 0 Relief!! |
| | 20 | - | Must be careful donning helmet otherwise CEP 0 can be brushed out of the ear canal | | 0 | | 0 |

| | Q33 Discomfort if forget to disconnect CEP from helmet | | | Minor irritation as earplugs pull | | | | | | | | | · | pulled out of ear | | | |
|---|--------------------------------------------------------------|----|-----|---------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|---|---------------------------------------------------------------------------------|---|--------------------------------------------------------|----------------------------------------------------------------------|---|----------------------------------------------------|-----------------------------------------|------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----|
| ı | Q33 Disc disc | ı | 0 | | 0 . | C | 0 | 0 | 0 | 0 | - | 0 | | - | 0 | 0 | 0 |
| | Q32 Problem don/doff w/gloves | | | | Negligible | | | | It is impossible. I have to don/doff without gloves on | | | | Must remove gloves to plug CEP in | | Need the hand agility and sensitivity to feel where plugs need to go | Cannot compress foam to place in ear | |
| l | Q32 Prob w/gl | | - | 0 | - | 0 | 0 | 0 | - | . 1 | 0 | 0 | - | - | - | - | |
| | Q31 Significant problem completing mission w/extra step | | | | In combat situation when you need to be airbome in a hurry it could interfere | | | | | | | | | If you touch earplugs at all it eventually falls out | | | |
| | Q30 Problem donning/doffing helmet w/CEP S c | | 1 0 | Must pull bottom of earcup out so as not to pull 0 out CEP from ear | 1 It takes longer to be ready for flight, also tends 1 to get tangled with NVG retaining cord | 0 | It takes some time donning so the CEP is not pulled out | 0 | 1 Slows down the process slightly 0 | 1 You now have to place your helmet on so it won't pull on the wires | 0 | 1 The fall out easily when putting on the helmet 0 | 0 | 1 Have to stretch helmet out farther | 1 Insert earplugs first, attach earplug to helmet, 0 pull helmet on carefully, keep earcups pulled out as you don helmet | 0 | 1 0 |
| | E | | _ | 2 | 3 | 4 | S | 9 | 7 | ∞ | 6 | 10 | = | 12 | 13 | 41 | 15 |
| | Q1 Unit location ID | 3. | - | | *** | 7 | • | Š | | ~ | 5 | | | | _ | _ | 1 |

| | | | | | | The state of the s | | |
|---------------------|------------------|-------------|---------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------------------------------------------------|
| Q1 Unit location | Q1 Unw Num | | Q30 Problem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | don/doff | Q33 Discom disconn | Q33 Discomfort if forget to disconnect CEP from helmet |
| . . | 16 | 1 | You must connect the CEP to the back of the helmet after donning it | 0 | | I can't seat them with gloves. But I can't seat foam earplugs with gloves either | 0 | |
| _ | 17 | - | Must use side to side method | 0 | 0 | | 0 | |
| ŕ | - | - | You must pull earcups back to place over plugs and back, nape strap has trouble sliding out. | 0 | - | Think about it. | - | It yanked on my ear. |
| | 7 | - | Must slip one ear on at a time to avoid pulling CEP out. | 0 | - | Less feeling | 0 | |
| , | ဗ | | Increases time | I It's just one more wire to put on, in addition to all the other equipment. It's not a habit yet. | - | It's easier to don with gloves off in order to plug in CEP to helmet. | 0 | |
| | 4 | - | Knocks plugs out | şand. | 0 | | 0 | |
| | 'n | - | Pulling earcups wider to pull it over the CEP. | 0 , | - | The gloves create a different feel to the CEP. Plus the CEPs are small and hard to move around with gloves on. | 0 | |
| | 9 | - | You really have to watch out for those wires. | Unless its an immediate faunch thing then I will just not use the earplugs. | - | I don't use the gloves because its impossible to find the plug for the CEP with them on. | | The plastic digs the ear canal. |
| | 7 | - | I have to pull the helmet out from my ears as I put it on to keep from knocking out the earplugs. | 0 | 0 | | 1 1 | Hurts my ears. I only did it once though! |
| | • | - | Takes more time. | 0 | - | Gloves on last | 0 | |
| | 6 | - | Makes them fall out | 0 | - | Connection is too small. | 0 | |

| Q33 Discomfort if forget to disconnect CEP from helmet | | 0 | | 0 | Pain when plugs are pulled from cars. | | 0 | 0 | | . 0 | C | 0 |
|--------------------------------------------------------------|----|--------------------|------------------------------------------------|---|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|---------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|----------------------------------------------------------------------------------------------------------------|
| oves | | Lack of dexterity, | feeling with gloves. | | | With the gloves on, it's hard to put the small tip/connector of the CEP into the plug on the helmet. | Have to remove gloves to connect CEP into jack. | You need to feel the device to fit it properly due to dexterity loss when wearing gloves. | | Gloves on is difficult. It however is no problem to put gloves on after inserting CEPs into ears, and connecting to the back of the helmet. | Can't do it vet. | |
| Q32 Prob w/gl | | - | | - | - | - | 1 | - | 0 | - | - | 0 |
| Q31 Significant problem completing mission | | 0 | | 0 | 0 | 0 | 0 | I If we are in a hurry Yes we hurry in aviation! Properly fitting the CEP is a hassle and induces more stress because it requires more time and patience when fitting. | 0 | 0 | 0 | 0 |
| Q30 Problem donning/doffing helmet w/CEP | | sdn | over the ears since the plugs come out easily. | | Helmet must go on before run-up so you can connect wires before gloves are donned. | You have to remember to connect the wires to the helmet after you put the helmet on. | | This is the real problem with this product. You must plug in the CEP in your ears, then put on your helmet and lastly plug in your CEP to the helmet. | | The sides of the helmet must be stretched outward just a little extra to ensure not to snag the CEP loose. | Have to put the wire in after donning the helmet. | You must grasp earcups and spread out to go over ears, to ensure you don't knock the earplugs out of your ear. |
| | | 1 | • | - | - | - | - | - | 0 | ~ | - | - |
| Q1 ID Num | | - | ć | 7 | m | 4 | 8 | 9 | 7 | ∞ | 6 | 10 |
| Q1 Unit location ID | 5. | 5 | | | | | | | | | | |

| Q33 Discomfort if forget to disconnect CEP from helmet | 0 | 0 | | 0 | 0 | | 1 The other pilots break the transducer wire on the right ear, next to the bottom or the transducer. | 0 | 0 | 0 | 0 | 0 | 1 | 0 |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------|---------------------------------------------------------------------|---|--------------------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|----|---|---|---|
| Q32 Probiem don/doff w/gloves | The gloves make it hard to fit into my ears and connect to the helmet. | Lose to much dexterity | Same as yellow earplugs. Fingers are not as nimble with gloves. | | I cannot plug them into the helmet with gloves on. | Can't be done with gloves. | | My hands are to clumsy with gloves. | | Can't get plug in helmet. | | | | |
| Q32 Prob w/gl | - | 1 | - | 0 | - | - | 0 | - | - | | 0 | - | - | 0 |
| Q31 Significant problem completing mission w/extra step | re. 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 s | 0 | 0 | 0 | 0 | 0 |
| Q30 Problem donning/doffing helmet w/CEP | I put the helmet on early in the run-up procedure. 0 It takes a little more time. | Takes longer | Pull the earcups out further to ensure they do not snare the wires. | | I have to get careful not to pull them out when the earcups contact the wires. | | A lot more time and more tenderness involved. | It takes longer. | You have to be really careful when using NVGs or the mic cord. The CEP cords have to be on top of everything else. | More careful placing helmet ear cups over ears to prevent them falling out, plus additional step of plugging in connector. | | | | |
| | | - | - | - | - | - | - | - | - | - | 0 | 0 | 0 | 0 |
| QI ID Num | 11 | 12 | 13 | 4 | 15 | 16 | - | 7 | m | 4 | \$ | 9 | 7 | ∞ |
| Q1 Unit location | 5. | | | | | | ý. | | | | | | | |

| Q1 Unit location | Q1 Num | | Q30 Problem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | don/doff | Q33 Disco discor | Q33 Discomfort if forget to disconnect CEP from helmet |
|---------------------|-----------|---|------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------------------------|------------------------|--------------------------------------------------------------|
| 6. | 6 | 0 | | 0 | ٥ | | ٥ | |
| ۲ | 10 | - | Have to pay close attention to the wires. | l It is awkward. | | Can't feel wires. | 0 | |
| : | - | - | Just have to plug in CEPs | 0 | 0 | | _ | It is rough getting pulled out of my ears |
| | 2 | 0 | | 0 | 0 | | | The helmet pulled the plugs from the ear canal |
| | m | - | I hold the earcups away from my ears so they don't pull the earplugs out | | - | It is hard to locate the connector on the helmet to plug the earplugs into with gloves on | 0 | |
| | 4 | | It' one more thing to do before you fly. | 0 | - | Putting any hearing protection w/gloves on is | 0 | |
| | 2 | 0 | | 0 | 0 | | 0 | |
| | 9 | | Must undo chin strap completely to don helmet. | 0 | - | I plug in the CEP into helmet prior to putting on my gloves. | 0 | |
| | 7 | - | Insert CEP, once helmet is on and aircraft is 100%, plug in CEP. | 0 | _ | CEP too small | 0 | |
| | •• | - | I must carefully fit the ear portion of the helmet over the ear plugs. | 0 | 0 | | 0 | |
| | 6 | 1 | Have to be careful going over ears. | 0 | 0 | | 0 | |
| | 10 | _ | Must be careful not to pull out plugs | | 0 | | 0 | |
| | = | - | Put CBP in first and position wire not to get caught up on helmet. | 0 | - | Can't feel the wires. | 0 | |
| | 12 | - | Put earplugs in first then wear helmet and | 0 | 0 | | 0 | |
| | 13 | 1 | At first the earcups had to be pulled outward significantly to keep the CEPs from being pulled out, but with experience its much easier. | 0 | - | I can't insert properly so I remove the gloves to insert the CEP. | 0 | |
| | | | | | | | | |

| Q33 Discomfort if forget to disconnect CEP from helmet | It pull out of your ears and breaks the speaker stems. | | | Just hurt if it didn't break. The earplug rip out of your ear. | Pulled on my ear canal. |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|
| Q33 Disc disc | - 0 | 0 0 - 0 | 0 0 | | 0 1 0 |
| Q32 Problem don/doff w/gloves | The recessed jack is hard to find when gloved. | Can't properly | with gloves on. Cannot find the plug-in w/gloves Never have tried it. Always put them in without gloves on. | Too hard to do with gloves. I usually put on my left glove then attach the wire and then put on my right glove. | I do it without gloves. Difficult to locate plug and plug it in the back of the helmet. |
| Q32 Prot w/gl | | 0 | - | | 1 0 1 |
| Q31 Significant problem completing mission w/extra step | | 0 0 0 | | When you are in a hurry it is hard to use them. | |
| olem donning/doffing helmet w/CEP | You must be careful to remove the plug prior to doffing the helmet. I put my gloves on after the helmet to allow for easy plugging in. I have to spread the helmet apart so it won't | Slower You have to hook up the wires - duh. | I have to hold the earcups open more. Not a problem. Need to spread the helmet/earcups more to slip over my ears w/o pulling out CEP. | Have to put them on out of the normal sequence I for me. I have to wait to strap in. Refuel is where most problems occur. Getting out then in. You have to connect the wire. | 0 Requires earcups to be pulled apart more to 0 prevent knocking plugs from ears. |
| | 1 | 0 1 1 | | | 1 0 1 |
| Q1 ID Num | 14 | 16 17 18 19 | 20 | 23 23 | 3 5 - |
| Q1 Unit location | 7. | | | | ∞ |

| Q1 Unit location | Q UN Num | | olem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | don/doff | Q33 Disco discor | Q33 Discomfort if forget to disconnect CEP from helmet |
|---------------------|----------|----------|---------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------|------------------------|--------------------------------------------------------------|
| æ. | | | | | | | | |
| | 4 | 0 | | 0 | - | Finger tip dexterity w/gloves does not allow for easy plug in of CEP. | - | Wires pulling earplug out. |
| | 2 | - | You must pull the earcups out further. | 0 | 0 | | 0 | |
| | 9 | 1 | | 0 | | | _ | |
| | 7 | - | | | - | | | |
| | •• | - | I must leave one glove off until my helmet and (CEP is on, | 0 | _ | See #31 | 0 | |
| | 6 | _ | Carefully spread the earcups and gently slide | | _ | Not anough feeling | - | |
| | | | | | - | to guide the helmet on without knocking the CEPs out of the ear. | - | |
| | 10 | - | Slower, more deliberate. | 0 | 0 | | 0 | |
| | = | 0 | | 0 | _ | Never wear gloves (impossible) | 0 | |
| | 13 | - | Must use caution not to dislodge the CEP when donning the helmet | 0 | 0 | I do not attempt | 0 | |
| | 13 | 0 | | 0 | - | Do it before you put your gloves on. | | Ripped it out of my ear! |
| | 14 | 0 | | But could be in a combat environment. | 0 | | 0 | |
| | 15 | <u>.</u> | | 0 | - | I can do it but is more difficult. | 0 | |
| | 16 | - | Takes more time to don. Also you have to make sure that everything is positioned right so you don't hang up the cord and pull it out during | 0 | - | I can't. My gloves have to be off otherwise there is not enough sensitivity. | - | Mild pulling throughout ear canal. |
| | 11 | | It is a pain to try to fit it up to the helmet. | I I'm in a time constraint and it always happens that I can't get it hooked up or it rips my ears off when I take it off. | _ | | | Ripped my ears off !!! |

| Q1 Unit location ID | QI Num | Q30 Prob | Q30 Problem donning/doffing helmet w/CEP | Q31 Significant problem completing mission w/extra step | Q32 Problem w/gloves | fon/doff | Q33 Discor discor | Q33 Discomfort if forget to disconnect CEP from helmet |
|------------------------|-----------|-------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------|----------------------------|----------------------------------------------------------------------|-------------------------|--------------------------------------------------------------|
| 9. | | | | | | | | |
| | | 0 | | 0 | 0 | | 0 | |
| | 2 | - | Added time chasing wires. | 0 | - | | 0 | |
| | 3 | - | Requires adjustment to get over plugs and wires. | 0 | | I can't do it. | 0 | |
| | 4 | 0 | | 0 | 0 | | _ | Yanks them out of ear. |
| | so. | - | Takes a few seconds more to get the helmet on so you don't pull the earplugs out. | 0 | gand | Your sense of feel is poor with gloves so its hard to feel the plug. | 0 | |
| | 9 | - | Have to remember to plug earplug into helmet. | 0 | - | Hard to find insert point on helmet. | - | Pulls CEP out of ears. |
| | 7 | - | Using earplug with helmet. | 0 | - | Unable when putting on helmet | 0 | |
| | ∞ | 0 | | 0 | - | | 0 | |
| | 6 | | More things to hook up! | 0 Just aggravating | - | Have to have gloves off. | 0 | |
| | 10 | - | Plug in connector after donning helmet | 0 | 0 | | 0 | |
| | Ξ | - | It takes some practice to put the earplugs in and put the helmet on without pulling the earplugs | 0 | - | I can't do it. | 0 | |
| | 12 | - | Takes a minute or so longer. | 0 | - | Can't do it. | 0 | |
| | 13 | - | Much more time is required. | 0 | - | Parts are too small and intricate. | | |
| | 14 | 1 | Earplugs in, cord over right shoulder, helmet on, plug in, climb in. | 0 | - | Hard to insert with gloves on. | | Yanks ears off. |
| | 15 | - | By virtue of more plugs and hardware. | 0 | - | Loss of dexterity - can't do it. | | Yanks ears off. |
| | 16 | - | Must be careful not to touch CEP. It will fall out 0 or become unseated. | 0 : | - | Impossible | - | Wires are pulled loose from |

| nning/doffing helmet w/CEP | Q1 Q30 Unit location ID Problem donning/doffing helmet w/CEP Num 10. |
|---------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|
| be a little more careful ensuring that the 0 go over my ears so as not to pull out s. | 1 I have to be a little more careful ensuring that the earcups go over my ears so as not to pull out the CEPs. |
| | Overall Total $N=152$ Yes = 121 $N_0=31$ $NR=0$ |

| | ID Rate Num donning/doffing | Rate ICS clarity | Rate ge (Male) | Rate gender clarity (Male) (Female) | Rate overall speech clarity | Rate noise reduction | Rate warning signals | Rate monitoring A/C noises | Q41 Rate weapons fire |
|----|-----------------------------|---------------------|-------------------|----------------------------------------|-----------------------------|----------------------|----------------------|----------------------------|-----------------------------|
| | | | | | : | | | | |
| _ | 4 | 7 | 7 | 7 | 7 | 8 | 7 | 3 | 9 |
| 7 | 9 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 |
| 3 | 3 | 9 | 4 | 4 | 9 | 9 | 9 | 9 | 9 |
| 4 | 60 | 9 | 9 | \$ | 9 | 4 | 9 | 8 | 4 |
| 2 | 8 | 7 | 7 | 7 | 7 | 9 | 9 | 5 | 4 |
| 9 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 4 | 7 |
| 7 | ю | 7 | 7 | 7 | 7 | 9 | 9 | 9 | \$ |
| 00 | 1 | 7 | 7 | 7 | 7 | 4 | 7 | 4 | 4 |
| 6 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 5 | S |
| 10 | 3 | S | 4 | 4 | vs | 4 | \$ | | |
| Ξ | ٣ | 7 | 7 | 7 | 7 | 7 | 7 | æ | 9 |
| 12 | 3 | 7 | 4 | 4 | 7 | s | 2 | 4 | 4 |
| 13 | 2 | 7 | 9 | 9 | 9 | 9 | 9 | 3 | 9 |
| 14 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 4 | 7 |
| 15 | 3 | 7 | 9 | 9 | 7 | . 9 | 4 | 3 | 5 |
| 16 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 3 | 9 |
| 11 | 4 | 9 | 9 | 9 | 9 | 4 | 4 | 4 | 4 |
| 18 | 3 | 7 | 7 | 7 | 7 | 9 | 9 | 9 | 9 |
| 19 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 9 | 9 |
| 20 | | 7 | 7 | 7 | 7 | 7 | 7 | 3 | 7 |
| 21 | Э | 7 | 7 | 7 | 7 | 7 | 3 | | 7 |
| 22 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 5 |
| 23 | | 9 | 9 | 9 | 9 | 9 | 4 | 4 | 4 |
| | | | | | | | | | |
| | | 7 | 7 | 7 | 7 | 7 | 7 | 2 | 7 |
| 7 | 4 | 7 | 7 | 7 | 7 | 9 | 2 | 4 | 7 |

| Q1 Q1 Unit location ID Num | Q1 Num | Q1 Q34 ID Rate Num donning/doffing | Q35 Rate ICS clarity | Q36 Rate ge (Male) | 136 Rate gender clarity (Male) (Female) | Q37 Rate overall speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire |
|-------------------------------|-----------|------------------------------------------|----------------------------|--------------------------|-----------------------------------------------|---------------------------------------|--------------------------------|--------------------------------|--------------------------------------|-----------------------------|
| 2. | | | | | | | | | | |
| | ю | 3 | 7 | 9 | 9 | 9 | 7 | 9 | 3 | ٠, |
| | 4 | 4 | 7 | 9 | 7 | 7 | 9 | 7 | 4 | . 4 |
| | S | 4 | 7 | 7 | 7 | 7 | 9 | 9 | . 2 | - \c |
| | 9 | 4 | 7 | 9 | 9 | 7 | 7 | 7 | ı en | o ve |
| | 7 | 4 | 7 | 7 | 7 | 7 | 4 | • • | · 4 | • 4 |
| | ∞ | - | 7 | 7 | 7 | 7 | 7 | 7 | . 0 | |
| | 6 | 4 | 7 | 7 | 7 | 7 | , v s | 7 | vo | |
| | 10 | 2 | 7 | 7 | 7 | 7 | e | | 4 | . 67 |
| | Ξ | 3 | 7 | 1. | 7 | 7 | 7 | 7 | 7 | |
| | 12 | 4 | 7 | 7 | 7 | 7 | 9 | 7 | . vc | ٠ ٧ |
| | 13 | 3 | 9 | 9 | 9 | 9 | 9 | 9 | , fu | o vo |
| | 14 | 2 | 7 | 4 | 4 | 7 | 7 | 7 | 5 | o ve |
| | 15 | 3 | 7 | 7. | 9 | 7 | 4 | 7 | 2 | , ₆ , |
| | 91 | 4 | 7 | 7 | 7 | 7 | 4 | 7 | 1 4 | . 4 |
| | 17 | 4 | 9 | 9 | 9 | 9 | 9 | 7 | · 60 | ٠ ٧٠ |
| | 18 | 3 | 7 | 7 | 7 | 7 | 7 | 7 | 4 | s ve |
| | 19 | 3 | 9 | 7 | 7 | 7 | 4 | 4 | 4 |) V- |
| | 20 | 4 | 7 | 7 | 7 | 7 | 4 | ۲. | 9 | , 4 |
| 3, | | | | | | | | | | • |
| | | 4 | 7 | 7 | 7 | 7 | 7 | 4 | 9 | 7 |
| | 7 | | 7 | 7 | 7 | 7 | 7 | 7 | 4 | . • |
| | 3 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | , , |
| | 4 | 9 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | |
| | 2 | 7 | 7 | 7 | 9 | 7 | 7 | 7 | | |
| | 9 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | | |
| | 7 | Э | 7 | 7 | | 7 | 4 | 7 | . 4 | - 4 |

| 8 4 6 6 6 6 6 6 6 7 4 4 4 4 4 4 4 4 4 4 4 | Q1 Q1 Unit location ID | Q1 ID Num | Q1 Q34 ID Rate Num donning/doffing | Q35 Rate ICS clarity | Q36 Rate ge (Male) | 336 Rate gender clarity (Male) (Female) | Q37 Rate overall speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|-----------------|------------------------------------------|----------------------------|--------------------------|-----------------------------------------------|---------------------------------------|--------------------------------|--------------------------------|--------------------------------------|------------------------------------|--|
| 44466464 8411 95884 4898 0 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | • | 4 | 9 | 9 | 9 | و | \$ | | 4 | 4 | |
| 4 4 2 8 4 4 8 4 8 2 1 1 1 3 2 8 8 4 4 8 9 8 6 8 6 8 9 8 9 9 9 8 9 9 8 9 9 8 9 9 9 9 | | 6 | 4 | 9 | 9 | 9 | 9 | 9 | · • | • •0 | | |
| 4 2 8 4 4 8 4 8 2 1 1 3 2 8 8 4 8 8 9 8 6 7 1 1 3 2 8 8 4 8 9 8 9 8 9 8 9 8 9 8 9 8 9 8 9 8 | | 10 | 4 | 7 | 7 | 7 | 7 | 9 | 7 | m | • • | |
| 2 & 4 & 8 & 4 & 8 & 4 & 8 & 4 & 8 & 4 & 8 & 4 & 4 | | Ξ | 4 | 7 | 7 | 7 | 7 | 4 | 7 | 4 | 4 | |
| E 4 4 E 4 E 2 I I 2 S E 2 E 2 E 2 E 2 E 2 E 2 E 2 E 2 E 2 | | 12 | 2 | 9 | 9 | 9 | 9 | 9 | 9 | 4 | 9 | |
| 4 4 8 4 8 6 7 1 1 2 8 4 4 8 6 7 1 1 1 2 8 4 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | 13 | 3 | 7 | 7 | 7 | 7 | 9 | 9 | m | · vo | |
| 4 8 4 8 6 7 1 1 2 3 3 5 6 7 7 7 7 8 8 9 8 8 9 9 7 7 7 7 7 7 9 9 9 9 | | 14 | 4 | 7 | 7 | 7 | 7 | 4 | 7 | E | 4 | |
| 8 4 8 6 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 | | 15 | 4 | 7 | 9 | 9 | 9 | 4 | 4 | 4 | 4 | |
| 4 | | 16 | 8 | 5 | 5 | \$ | 5 | 4 | | 4 | 4 | |
| 0 C C 4 8 C C C C C C C C C C C C C C C C | | 17 | 4 | 4 | 4 | 4 | 4 | 4 | 1 | 4 | | |
| 0 r r 4 x r r r r r r r r r | | | | | | | | | | | | |
| 2 2 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | - | m | 7 | 9 | 9 | 9 | 9 | 7 | 9 | 9 | |
| 3 1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | 7 | 2 | 7 | 7 | 7 | 7 | 7 | 7 | \$ | æ | |
| 4 1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 | | 3 | - | 7 | 7 | 7 | 7 | 7 | 7 | 9 | 9 | |
| 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | 4 | - | 4 | 4 | 4 | 4 | 4 | 4 | 4 | 4 | |
| 6 2 5 5 4 8 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | s | 9 | 7 | \$ | S | 5 | 9 | 9 | 9 | 9 | |
| 7 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 3 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | 9 | 2 | \$ | | | | \$ | v | 4 | 3 | |
| 8 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 3 3 7 7 7 7 7 7 3 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | 7 | 3 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | |
| 9 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 3 3 3 7 7 7 7 7 7 3 3 7 7 7 7 7 3 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | ∞ | 2 | 7 | 7. | 7 | 7 | 7 | 7 | 5 | S | |
| 1 7 7 7 7 3 7 3 3 7 3 3 3 3 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 3 | | 6 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | |
| 1 7 7 7 7 3 7 3 2 4 5 5 5 5 7 7 5 3 3 7 7 7 7 7 7 7 7 4 6 7 7 7 7 7 7 7 5 3 7 7 7 7 7 3 | | | | | | | | | | | | |
| 2 4 5 5 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 3 | | _ | | 7 | 7 | 7 | 7 | 3 | 7 | 3 | | |
| 3 3 7 7 7 7 7 7 8 4 6 7 7 7 7 7 7 7 7 5 3 7 7 7 7 7 3 | | 7 | 4 | \$ | \$ | 5 | 5 | 5 | 7 | \$ | ۶. | |
| 4 6 7 7 7 7 7 7 5 3 7 7 7 7 3 | | 3 | 3 | 7 | 7 | 7 | 7 | 7 | 7 | ٧٢ | 7 | |
| 5 3 7 7 7 7 7 3 | | 4 | 9 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 9 | |
| | | 8 | 3 | 7 | 7 | 7 | 7 | 7 | 7 | 3 | | |

| Q1 Q1 Unit location ID Num | | Q34 Rate donning/doffing | Q35 Rate ICS clarity | Q36 Rate ge (Male) | 336 Rate gender clarity (Male) (Female) | Q37 Rate overall speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire |
|-------------------------------|----------|--------------------------------|----------------------------|--------------------------|-----------------------------------------------|---------------------------------------|--------------------------------|--------------------------------|--------------------------------------|-----------------------------|
| Š. | 9 | æ | 7 | 4 | 4 | 9 | y | , | , | |
| | 7 | ٧n | 7 | 7 | 7 | 7 | , , | - 1 | , , | 4 1 |
| | ∞ | 4 | 7 | 7 | 7 | | | | - 4 | - ' |
| | 6 | en | 7 | 7 | 1. | 7 | , « | | o • | ۰ ، |
| | 10 | 4 | 7 | 5 | 9 | 7 |) 4 | | į t | 4 4 |
| | = | 4 | 7 | | | 7 | | | | nı |
| | 12 | | 7 | 7 | 7 | 7 | | . vo | · | n v |
| | 13 | 4 | 7 | 7 | 7 | 7 | 4 | · F | ٧ ج | o |
| | 14 | 4 | 9 | 9 | 9 | 9 | · ve | | T = | |
| | 15 | 9 | 7 | 7 | 7 | 7 | 4 | , , | | |
| | 16 | 3 | 7 | 7 | | | | | t < | |
| .9 | | | | | | | | • | ; | |
| | - | 5 | 9 | 9 | 9 | 9 | 80 | v | ¥ | • |
| | 7 | | 9 | 9 | 9 | • • | | | , c | o t |
| | e | 4 | 7 | 7 | 7 | 7 | 4 | | , , | |
| | 4 | 2 | 7 | 7 | 7 | 7 | 7 | · ve | | † - |
| | 2 | 4 | 7 | 7 | 7 | 7 | 7 | | | + r |
| | 9 | 4 | 7 | 7 | 7 | 7 | · 60 | | ~ 64 | - (|
| | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | | 4 1 |
| | ∞ | 4 | 7 | 7 | 7 | 7 | 4 | 7 | · e* | - v |
| | 6 | 4 | 7 | 9 | 7 | 7 | 9 | • • | n ve | n u |
| 7 | 10 | | - | - | - | | 1 | - | , w |) = |
| : | - | 4 | , | • | r | , | • | 1 | | |
| | , | - (** | - 1 | - t | - t | ~ 1 | , | 7 | 7 | 7 |
| | ١ ، | n (| | • | _ | 7 | 4 | 7 | 7 | 3 |
| | . | m | 7 | 7 | 7 | 7 | 9 | 7 | 4 | 9 |

| Q1 Unit location ID | Q U Num | Q1 Q34 ID Rate Num donning/doffing | Q35 Rate ICS clarity | Q36 Rate ge (Male) | Q36 Rate gender clarity (Male) (Female) | Q37 Rate overall speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire |
|------------------------|-----------------------------------------|------------------------------------------|----------------------------|--------------------------|-----------------------------------------------|---------------------------------------|--------------------------------|--------------------------------|--------------------------------------|-----------------------------|
| 7. | 4 | 3 | 9 | 9 | 9 | 9 | 2 | 4 | 4 | 2 |
| | S | 9 | 7 | 7 | 7 | 7 | 7 | 7 | 9 | 9 |
| | 9 | 4 | 7 | 7 | 7 | 7 | 3 | 7 | 7 | 4 |
| | 7 | 3 | 9 | 9 | 9 | 9 | 9 | 7 | 9 | 9 |
| | ∞ | 7 | 7 | 9 | 9 | 7 | 7 | 1 | | 7 |
| | 6 | 4 | 9 | 9 | 9 | 9 | 4 | 9 | 4 | 5 |
| | 10 | 4 | 7 | 7 | 4 | 7 | 7 | 7 | 7 | 7 |
| | ======================================= | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 4 |
| | 12 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 4 | 4 |
| | 13 | 4 | 7 | 7 | 7 | 7 | 4 | 7 | 4 | 9 |
| | 14 | 9 | 7 | 4 | 4 | 7 | 9 . | 7 | 9 | 9 |
| | 15 | | 7 | 7 | 7 | 7 | 7 | 7 | 3 | 9 |
| | 16 | 4 | 7 | 7 | 7 | 7 | 5 | 7 | ν. | 4 |
| | 11 | 5 | 5 | \$ | 4 | 5 | 5 | S | 'n | ٧٢ |
| | <u>∞</u> | 4 | 5 | 2 | \$ | 5 | 5 | S | 4 | v |
| | 19 | 2 | 7 | 7 | 9 | 7 | 3 | 7 | 8 | 33 |
| | 20 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 8 | 7 |
| | 21 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 2 | 7 |
| | 22 | 2 | 7 | 9 | 9 | 9 | 4 | 4 | 4 | 4 |
| | 23 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 9 |
| ∞ | | | | | | | | | | |
| | _ | 4 | 7 | 7 | 9 | 7 | 7 | 7 | 4 | 7 |
| | 7 | 9 | 7 | 9. | 9 | 7 | 2 | 9 | 7 | 2 |
| | 3 | 3 | 9 | 9 | 9 | 9 | 4 | 9 | S | 4 |
| | 4 | 2 | 7 | 9 | 9 | 7 | 7 | 9 | 3 | 4 |
| | 2 | ٧n | 7 | 7 | 7 | 7 | 7 | 7 | 3 | 9 |

| Q1 Q1 Unit location ID Nun | QI Num | Q34 Rate donning/doffing | Q35 Rate ICS clarity | Q36 Rate gei (Male) | 236 Rate gender clarity (Male) (Female) | Q37 Rate overall speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire |
|----------------------------------|-----------|--------------------------------|----------------------------|---------------------------|-----------------------------------------------|---------------------------------------|--------------------------------|--------------------------------|--------------------------------------|-----------------------------|
| ∞i | 9 | | ĸ | 4 | 4 | 4 | 4 | | | |
| | 7 | good | - | • | | • | | | | |
| | ∞ | 3 | 7 | 7 | 7 | 7 | e | 4 | vo | 6 |
| | 6 | 3 | 'n | 40 | ٠, | 5 | S | 7 | · 60 | , ka |
| | 10 | 2 | 7 | 7 | 7 | 7 | 4 | 7 | 4 | • |
| | 11 | 4 | 7 | 9 | 9 | 9 | 7 | m | · m | 7 |
| | 12 | 4 | 7 | 7 | 7 | 7 | 8 | 7 | 4 | - 4 |
| | 13 | es | 7 | 7 | | 7 | 7 | 7 | 4 | |
| ٠ | 14 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | - 4 |
| | 15 | 33 | 4 | 4 | 4 | 4 | 4 | 4 | 4 | . 4 |
| | 16 | 2 | 9 | 9 | 9 | 9 | e | 7 | 4 | . 4 |
| | 17 | 2 | S | ď | 4 | \$ | S | 4 | · v | - 4 |
| 6 | | | | | | | | | , | |
| | - | S | 7 | 9 | 9 | 7 | 9 | 5 | vo | |
| | 7 | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 |
| | 6 | 3 | 7 | 7 | 7 | 7 | S | 5 | 4 | 7 |
| | 4 | 7 | 7 | 7 | 7 | 7 | 9 | 9 | . 9 | 7 |
| | 2 | 9 | 7 | 9 | 9 | 7 | 7 | 7 | 7 | 7 |
| | 9 | 4 | 9 | 9 | | 9 | 4 | 9 | m | |
| | 7 | 3 | 7 | 2 | 2 | S | 9 | 9 | 9 | 9 |
| | œ | 4 | 7 | 7 | 7 | 7 | 7 | 7 | 7 | 7 |
| | 6 | 3 | 7 | 7 | 4 | 9 | 9 | | 9 | |
| | 9 | 4 | \$ | sc. | 2 | 5 | s | 5 | 4 | 9 |
| | Ξ | 3 | 4 | 4 | 4 | 4 | 4 | 4 | 4 | |
| | 12 | 3 | 7 | 4 | 4 | 7 | 7 | 7 | 4 | 4 |
| | 13 | 3 | 7 | 4 | 4 | 7 | 7 | 7 | ю | 4 |

| Q1 Unit location | OI II Num | Q1 Q34 Q35 Unit location ID Rate Rate ICS Num donning/doffing clarity | Q35 Rate ICS clarity | Q36 Rate ge (Male) | nder clarity (Female) | Q37 Rate gender clarity Rate overall (Male) (Female) speech clarity | Q38 Rate noise reduction | Q39 Rate warning signals | Q40 Rate monitoring A/C noises | Q41 Rate weapons fire |
|------------------------------------------------------|-----------|-----------------------------------------------------------------------|-------------------------------|-------------------------------|--------------------------|---------------------------------------------------------------------|--------------------------------|--------------------------------|--------------------------------------|--------------------------------|
| 9. | | | | | | | | | | |
| | 14 | 4 | 9 | 9 | 9 | 9 | v | 9 | 3 | 9 |
| | 15 | | 4 | 4 | 4 | 4 | 4 | | | |
| | 16 | | 7 | 7 | | 7 | 9 | 9 | ٣ | |
| 10. | | | | | | | | | | |
| | - | | 7 | 7 | | 7 | 9 | | 4 | 8 |
| Overall Total N = 152 M = 3.7 SD = 1.3 NR = 12 | N 15 | | M = 6.6 SD = 1.0 NR = 0 | M = 6.3 SD = 1.1 NR = 3 | 6.2 1.1 9 | M = 6.5 SD = 0.9 NR = 3 | M = 5.6 SD = 1.5 NR = 1 | M = 6.2 SD = 1.4 NR = 6 | M = 4.7 SD = 1.5 NB = 4.7 | M = 5.3 SD = 1.4 NB = 17 |

| Q1 Unit location | Q1 ID Num | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | 1 | 0 | Dane consetenction of CED The CED and a later |
| | 7 | 0 | Cometimes Total and will denote incide the control of the control |
| | | | combonines. The spots will develop inside the ear canal it plugs are inserted too far in. |
| | 3 | 0 | See above |
| | 4 | 0 | |
| | \$ | | |
| | 9 | I They are too fragile. I love the CEP. They take a little extra time to install but the benefits are worth it. | The cord catches on things and will dislodge from the ear. It is very difficult to install them in-flight |
| | 7 | 0 | The only problem I have with the CEPs is that over time, extended mission |
| | | | over 2 hours, the CEPs tend to slop out of your ears. Also the center post tends to dig into your inner ear over long missions witch makes them |
| | o | | uncomioriable. |
| | 0 | | |
| | 6 | 0 | |
| | 10 | | |
| | 11 | 0 | |
| | 12 | 0 | |
| | 13 | 0 | Once the wires are strengthened the device will be better |
| | 14 | | No problems |
| | 15 | I They are not built to handle serious wear and tear. | During extended periods of wearing the CEPs they make the ear canal ache |
| | 16 | 0 | 'Allon mimo mo ano allon |
| | 17 | 1 They are too fragile. Mine broke after roughly 25-30 hours of use and my ALSE technician was not trained or probably equipped to repair the items | |
| | 18 | 0 | |
| | 19 | 0 | Sore ear canals |
| | 20 | 1 easy to lose | |
| | 21 | 0 | Continuous use (4 days in a row of 4-hour flights each day) results in ear |
| | 22 | | canal sensitivity |
| | į | | |

| | S G S | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|----|----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | 23 | 0 | |
| | | 0 It blocks out all aircraft noise. | I think the more durable parts are the way to go when making this final CEP because they go thru alot in the field and we need an inexpensive, more durable unit to provide to pilots to improve communications between aircrews, ground elements, ATC, & Commanders. |
| | 2 | 0 | Very delicate. |
| | 3 | 0 | |
| | 4 | 0 | Make the foam stiffer. |
| | S | 0 | In reference to monitoring noise generated by the aircraft, blocks out A/C noise and vou can't hear engine and rotor noise. |
| | 9 | 0 | |
| | 7 | 1 Foam tips fall apart after second wash and cannot stay compressed to insert in | Foam tips not durable after first wash. |
| | ∞ | 0 | The Velcro on the left wire will drive you nuts when it falls off the Velcro in the back of your helmet. The threaded stud needs to be flexible so as to conform to the inner ear canal. |
| | 6 | 0 | |
| | 01 | 1 Caution/ warning tones were too loud. I am used to yellow foam earplugs while flying - caution tones just right | |
| | = | 0 | Wires getting caught on other items strapped to my head or body. I have had CEPs for close to a year with no foam replacement. Mine are no good. |
| | 12 | 1 The only problem that I have, is that they are made to flimsy. They need to be hardened some way. As I said, I'm on my third pair | Mine have broken right at the ear foam, where the wire connects to the foam |
| | 13 | • | Long wire caught on vest and pulled CEP out of ear. While trying to adjust this the wire broke |
| | 14 | 1 CEP offers better hearing of radio traffic. A wider range of ear plug portions and stronger cord connection to plug screw portion would greatly increase the lifetime of these plugs. Aviators are very rough on equipment. Build them to | |
| | 15 | 0 | |
| | 16 | 0 | |
| | 17 | 0 | |

| Q1 Unit location | QI ID Num | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2. | 18 | 0 They broke within 75 hours, very uncomfortable. Maybe I was sized wrong. | Wires easily caught on objects and pulled out of ears. When foam tips are hot and moist they will not stay collapsed long enough to insert into ear Broke less than 75 hours and not comfortable |
| 3. | 20 | 0 | |
| | - 2 | 0 I Stem failure - earplug stuck in ear during flight | Se ahove |
| | ю | | There is a need for ICS performance. The CEP is a good interim fix, but it is figule and easy to lose. It takes extra time to don helmet especially when neing MACE. |
| | 4 . | 0 | 100 E 14 C 25 |
| | e 9 | 0 0 | The potten anniled and hate Avina with one than |
| | ۲ % | Cautions/warnings too loud Not a big problem but just one more thing to add to a long list of small | The Bossess operated materials without titelli |
| | o | | |
| | 01 | Hard to hear aircraft noise i.e. engine etc | They are not very durable overall Tones are too loud |
| | = 2 | Caution warning advisory signals extremely loud | Advisories too loud |
| | 1 21 | | Doesn't stay in my ear well Ear piece wires seem way to flimsy-they break at ear piece commonly. I was very careful not to put undo pressure/stress on system, and after 100 hours |
| | 14 | 0 | or hymes, one whe reached its useful life and droke at ear piece. |
| | 91 | 1 I no longer use CEP for two major reasons: I. They are too uncomfortable. 2. To adjust the ICS to hear radios and cockpit communication, the aircraft caution and warning audio becomes entirely too loud | |
| | 11 | 0 | |

| Q1 Unit location | ₽ ⊟ | Q42 Advers | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|------------|---------------|------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| | Num | | | D |
| 4. | - | 1 Disc | Discussed it in earlier questions | It clides out too eacily. Need emaller but more course enume and luce |
| | . 2 | 0 | | it situes out two easity. Iveed sittaties out intole situg eaplings. |
| | e | 0 | | |
| | 4 | 1 They | 1 They are uncomfortable | |
| | 2 | 0 | | |
| | 9 | 0 | | The foam changed after washing. It no longer holds its reduced size to |
| | 7 | 0 | | |
| | ∞ | 0 | | |
| | 6 | 0 | | They fall out. |
| 5. | | | | |
| | - | 0 | | |
| | 2 | 0 | | |
| | 3 | 0 | | Difficulty getting them to stay in ear canal and some ear canal pain because |
| | 4 | 0 | | The speaker end of the wires would be more comfortable if they were |
| | | | | smaller, or if they were formed and fitted for each ear. |
| | 8 | 0 | | Some ear pain is associated with the insert but will change to a smaller size when available. |
| | 9 | 0 | | |
| | 7 | 1 The even | The installation portion. Soldering wires together makes weak wires and eventually will break. | See #12 |
| | • | 0 | | No problems |
| | 6 | 0 | | |
| | 10 | 0 | | No problems encountered so far. |
| | 11 | 0 | | |
| | 12 | 1 Duri | 1 During engine start I cannot hear the igniters pop or hear the engine light off. | |
| | 13 | 0 | | Snags when putting the helmet on and taking it off. |
| | 14 | 0 | | |

| Q1 Unit location | Q1 Num | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|-----------|----------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 5. | 15 | 0 | |
| , | 16 | | CEP make caution/warning signals way to loud. |
| ં | 1 | | The CEPs were not made durable enough for ARMY aviation. The wires, the |
| | | | tips, and the harness assemblies have all had major failures within the first 3 months. Some tips broke on initial issue to the user, causing what I think should be a ODR issue |
| | 7 | 0 | פונסמים טל מ לבור ושמעל. |
| | 3 | 0 | The warnings are extremely fourd but that is not a CED morphoun |
| | 4 | . 0 | and the content of the car of the car problem. |
| | \$ | 0 | |
| | 9 | | |
| | 7 | . 0 | |
| | 00 | | Wire laying on outer ear causes hot spots, wire is too long and gets caught |
| | 0 | | in shirt, seat beits, vest, etc. |
| | ^ | | The only problems I had were noted on the cover sheet (1 and 3). Wire breakage at transducer and screw tip breaking off. |
| ı | 10 | 1 Can't hear as well. | They pull out when donning, extremely uncomfortable, can't hear as well, does not reduce noise as well. |
| 7. | 1 | 0 | |
| | 2 | 1 Only that the CEPs would sometime operated intermittently, but nothing significantly | |
| | 6 | 0 | The only problem I have is the wore getting caught and pulling on the |
| | 4 | | carpiugs when I turn my nead |
| | 2 | 0 | |
| | 9 | 0 | |
| | 7 | Aircraft audio tones extremely loud. | |
| | ∞ | 0 | The problems I have encountered you have already addressed. |

| Q1 Unit location | Q1 ID Num | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|-----------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 7. | 6 5 | | Problem getting the right size foams. |
| | 1 1 2 | 0 0 | Wire pulls CEP out of ear. All problems were addressed in the questionnaire |
| | 13 | The wire harness is difficult to lay around the ear properly. It will cause some minor discomfort if harness is not monarly routed around the sor | I had a wire break at the CEP when removing my helmet. I really like them. The wires tend to snag on harnesses and connector within the cockpit. |
| | 15 | | |
| | 91 | 0 | Forgetting to unhook before doffing. |
| | 11 | | Don't use. Don't like it. |
| | 18 | 0 | Better quality |
| | 61 | . 0 | |
| | 20 | 0 | Slight discomfort after 3-4 hour flights. Ears get a bruised feeling occasionally. |
| | 21 | 0 | Only problem is the slight "hot spot" mentioned in Q26. |
| | 22 | 0 | |
| • | 23 | 0 | |
| ó | - | 0 | Availability of parts-we do not have enough helmets or CEPs. Sometimes the wires can get over my ear and between earning and cause discomfort |
| | 7 | 0 | The state of the s |
| | 3 | 0 | None that have not been discussed earlier. |
| | 4 | 0 | |
| | v | 0 | The foam inserts in the helmet push on the CEP ear plugs which cause ear pain. |
| | 9 | | |
| | 7 | | |
| | ∞ | 0 | No major problems. |

| Q1 Unit location | Q1 DNum | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|---------------------|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ထံ | 6 | 0 | My left ear canal is now tender from everyday use, resulting in just placing |
| | 10 | I Caution warning and advisory signals are always full volume. I do not wear CEPs during contact training for this reason. | ute CER device near my text ear for now. If the ear piece were smaller, it would be more comfortable. If the foam plugs were more firmer, they would be easier to insert |
| | 11 | | |
| | 71 | CEP. | Foam inserts do not last very long. Wires are prone to breakage at the |
| | 13 | 0 | I cannot use the foam earplug without significant modifications. I always had to use the rubber triple flange earplugs, due to problems fitting the foam ones. The foam ones wear out too fast and nose a problem in replacement |
| | 14 | 0 | The state of the s |
| | 15 | 1 Overall clarity/noise reduction was not improved only amplified. The CEP does not correct deficiencies in the OH-58D ICS system. | I do not like wearing earplugs so my opinion is biased. |
| | 91 | 1 It takes some time to get used to. Its not as easy as just putting on a helmet. However after it is used for a while you get used to donning and doffing procedure and the sequence you must go through to get it on. | Mild pain in the ear canals after 2 hour flights. Donning procedure requires a sequence that must be followed or CEP will be pulled out. Basically the CEP must he donned just prior to helmet use |
| c | 17 | | of a mass of dominary protein to natural tase. |
| <i>.</i> | guess | | 11110 |
| | 5 | | nave not worn CEP long enough. |
| | ю | 0 | Wax in the plug canal, broken wire right plug, uncomfortable after a period of time |
| | 4 | 0 | |
| | S | | |
| | 9 | 0 | |
| | 7 | 0 | With doors off aircraft has significant noise. |
| | •• | 0 | |
| | 6 | 0 | CWA too loud! |
| | 10 | 0 | |
| | 11 | 0 | |

| Q1 Q1 Unit location ID Num | Q1 ID Num | Q42 Adverse effects of CEP | Q43 Problems encountered while wearing CEP |
|----------------------------------|-----------------|-------------------------------|------------------------------------------------------------------------------------------------------------------------|
| 9. | | | |
| | 12 | 0 | Donning the helmet with CEP can't be done with flight gloves on. |
| | 13 | 0 | |
| | 14 | 0 | |
| | 15 | 0 | |
| | 91 | 0 | |
| 10. | | | |
| | - | 0 | With all noise/radio/ICS levels in a comfortable range a CWA message/tone in an OH-58D is extremely loud and annoying. |
| Overall Total N = 152 | | Yes 27 | |
| | | | |

| Q1 Unit location | Q UN Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 1. | - | The need to be more accessible and should be fielded to all helicopter pilots | 7 |
| | 2 | Great! Use to wear earplugs occasionally resulting in hearing difficulty in the cockpit. I wear CEPs all the time now. I hear perfectly and I am also protected from outside noises. | 7 |
| | æ | Good noise attenuation during gunnery but needs to be a little more durable. | V) |
| | 4 | No big problems yet. Haven't flown with them much yet. | No. |
| | ٧٠ | The benefits greatly outweigh the time and difficulty putting them on. | 7 |
| | 9 | Very nice increase in hearing ability of ICS, radios. The caution/warning tones are excessively loud now. | |
| · | 7 | Overall CEPs are a valuable asset. They only have a few minor problems but overall they improve our ability to accomplish out mission. | 7 |
| | 60 | I would rather the original problem be fixed instead of giving me another piece of equipment. Fix the ICS problem and throw out your temporary fix. While you are at it give me a helmet with active noise cancellation. The computer in the aircraft will tell me of any problems prior to me hearing any change in engine noise anyway. | 7 |
| | 6 | They are great - you just really need to take care of them. | 7 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| | 01 | Slightly better hearing protection, slightly better quality audio. Benefits aren't really worth the hassle of use. Plugs leave ear canals feeling they have been bored out with a cleaning brush. | E |
| | = | | , |
| | 12 | Need to be more rugged | , |
| | 13 | | 9 |
| | 41 | Bulk of the transducer | 1 |
| | 15 | They significantly increase the clarity of radio traffic | 7 |
| | 16 | EXCELLENT! Need to field all units, back fill others. This has improved crew safety and communications immeasurably | 7 |
| | 17 | ICS is definitely better, however the fragility of the systems lends itself to breaking | e |
| · | 80 | | 7 |
| | 19 | Definitely needed device. Just come up with a better design. | 7 |

| Q1 Unit location | Num Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| <u>.</u> | 20 | This is one of the Army's best ideas. The radios in the OH-58D(I) are hard to hear without the CEPs. The CEPs help dramatically in the ability to hear and comprehend the radio traffic. You don't have to focus all your attention on the radios with the CEPs in. This is a great product. | 7 |
| | 21 | We absolutely need them! They could be a little louder | 7 |
| | 22 | The entire Army should have them | 7 |
| | 23 | | 9 |
| | - | The CEP is long overdue. Excellent!! My first CEP broke but I was able to acquire another by someone leaving and I have taken better care of it. | , |
| | 2 | Excellent | 7 |
| | 6 | I think there is a world of difference with the CEP. Noise is reduced and clarity over the radio is so much better. | 9 |
| | 4 | Getting to the point of too many wires on the head: helmet, ODA, goggles and neck strap, CEP and lip light. | 7 |
| | s | Other than the wire getting caught on the vest and other equipment, I thought the CEPs were a great improvement over just the helmet. I couldn't wear yellow ear plugs because I could not hear at all. This is a great improvement. | 7 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 2. | 9 | Much easier hearing crew members as well as the radios. | 7 |
| | 7 | Great product. Continue to improve and field to everyone. | 7 |
| | 60 | I used to wear yellow foam earplugs all the time. Once I started using CEPs I got addicted to being able to understand the radios. But they are so painful after prolonged periods that now I don't use any additional hearing protection. But I still don't use them except for gunnery. | W |
| | 6 | Commo is much more easily understood while using CEPs, however if you use CEPs for 50 more hours and then revert back to yellow earplugs, you can have almost nothing! | 7 |
| | 01 | Significantly improved cockpit communication | 7 |
| | = | Great device but need more replacement foam inserts! | 7 |
| | 12 | I like them a lot. The difference between not wearing them and wearing them is night and day. | 7 |
| | 13 | Foamy does a good job with noise levels. It is a pain in the ass by getting caught where vest and collar meet. It would pull the CEP slightly from the ear. Plus the CEP is cheaply built. The cost is extremely high. | 9 |
| | 14 | | 9 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 2. | 15 | After using CEPs exclusively and then having them break, I had to go back to yellow ear plugs with great reduction in hearing performance. I had gotten very used to being able to hear communications clearer. | 9 |
| | 91 | CEPs are great! I was really upset when mine broke. Can't wait to get another pair. | 7 |
| | 11 | | 9 |
| | 18 | Good item if wires and foam tips are improved. Use same material as yellow foam earplugs?! | ٢ |
| | 19 | Though not comfortable, I could definitely hear all radios and ICS better | |
| | 20 | I hope I never have to go back to flying wout CEPs or something like them. The benefits far exceed the discomfort I have to put up with. If they were made more comfortable they would be better yet. | 7 |
| ě. | - | | 7 |
| | 7 | I like it. Need more durable product | 7 |
| | m | Sometimes it gets hung up when turning head which could distract pilots at critical times during flight. It enhances mission performance when you can actually head what is being transmitted over the ICS and radios | 7 |

| 10 | 5 | 044 | 045 |
|---------------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|
| Unit location | ID Num | General comments about CEP | Rate overall value of CEP |
| 3, | 4 | A/C needs voice activated ICS due to work load and the need for cockpit communications. | 7 |
| | S | The CEP works great but it is a bit too fragile the wires are too weak and the location needs to be moved | 7 |
| | 9 | It has been a pleasure, especially when flying from the right seat. It has added a significantly wider volume range. I can turn a radio volume knob all the way down and still adequately hear and understand speech on that radio. I never advocate crewmembers pulling their ICS pins, and do not have to when utilizing the CEP. It makes flying with doors off much more pleasurable. | |
| | 7 | Viable product. I endorse it | 7 |
| | ∞ | These earplugs seem to me a bandaid over the larger problem. Rather than investing any more money, time or equipment on these earplugs how about putting some better ICS boxes in the aircraft. The aircraft at FT Rucker had VOX boxes in the aircraft. Those boxes were more than adequate. I used both my SPH-4B and HGU-56 with earplugs with the VOX box and had plenty of volume in all flight modes. | 2 |
| | 6 | After getting used to them I have found them to be an outstanding product | 9 |
| | 10 | | 7 |
| | = | Love them! | 7 |
| , | 12 | Works well can hear radios well reduces aircraft noise | 9 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 3. | 13 | Great. Help hearing co-pilot over noise of aircraft/radios. I would consider this essential to good cockpit crew co-ordination and communication. This is common to everyone I know who uses these plug phones. Also, Also, I never pulled the CEP's from ears by the wires. Please provide durable plugs ASAP. | 7 |
| | 14 | Excellent product!! I do not think I could fly without it now. | 7 |
| | 15 | | ٧. |
| | 16 | Due to the task load of the CPO in the OH-58D, the CPO must use "hot mic" on the ICS. This degrades the level of audio clarity. This aircraft must have "voice activated" (VOX) ICS, as a minimum at the CPO station. This will greatly improve the communication clarity of the aircraft. I have used these at Ft rucker and was well pleased with them. | 2 |
| | 17 | | |
| 4 | - | The communications clarity is excellent - the improvement is worthwhile. We need just minor fixes. | v |
| | 2 | I love them. Try to improve. | 7 |
| | æ | Even with the added time and some discomfort, the CEPs are far superior to the older helmets. | |
| | 4 | Don't like it. | - |

| Q1 Unit location | QI Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 4. | S | Overall it is a good system but it needs to have a more durable wire and connection. Must be a stronger wire. | 9 |
| | 9 | It looks goofy with the large ear cuffs. | s, |
| | 7 | I like the CEP much better then the old SPH-4 but the shape leaves a little to be desired. The SPH-4 was a better looking helmet. | 7 |
| | œ | | ٠ |
| | 6 | | 7 |
| ن | - | CEPs work well in clarifying speech and being able to communicate in the cockpit. | 7 |
| | 7 | | 'n |
| | м | Extend the length of the helmet chin strap to ease helmet donning with earplugs installed and shorten slightly the length of the tube inside the foam on the plug itself to ease ear canal pain. The CEP has greatly increased the safety of flight in the OH-58D. Do not take it away. I can hear the radios and my co-pilot at all time now. | 7 |
| | 4 | | 7 |

| Q1 Unit location | QI ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 5. | S | They are awesome! The ability to hear everything is so much better with these CEPs I can live with a little discomfort. The safety benefit of being able to hear the other pilot is also a giant plus. Doors off flying is so much better now. | 7 |
| | 9 | Just purchase the BOSE headsets and put them into our helmets, it's a superior proven product. Good idea but poor design! Too cumbersome when doing exercises. Cannot put helmet on and go. You are required to "fiddle with it". | ٧. |
| | 7 | Makes a big difference in hearing radios and internal communications. | |
| | 90 | The ARMY has finally purchased a piece of equipment that not only is functional, but doesn't burden the soldier with its use. Thanksl | |
| | 6 | | 7 |
| | 10 | The CEP has improved the ICS systems clarity and radio clarity 100%. Especially with doors off. I think the CEP is a good improvement for OH-58D pilots. | 7 |
| | Ξ | An excellent system that improves ICS communication and reduction in noise. I would not want to fly without the CEP after flying with it. | 7 |
| | 12 | | , , |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 5. | 13 | All ICS and radio communications is significantly better. Crew coordination is better - radio management is much easier since the pilot doesn't have to have all radios turned all the way up in order to hear anything. The number of "say again" and "what did you say" have significantly decreased. | 7 |
| | . 41 | | 9 |
| | 15 | | 7 |
| | 16 | Correct piece of equipment. | 7 |
| · • | · | Reorder problem- PCS of pilots caused severe shortage of CEPs available to new arrivals. CIF was making ALSE turn in the helmets as a complete kit with CEP installed. Can't get thru normal supply but as GSA item causing problem due to lack of funds. Once I punch a hole thru the back of the earcup black plastic liner, that condemns the helmet for turn-in procedures - again causing a reorder problem for the ALSE maintainers. | v o |
| | 7 | I would like to see an improved earphone assembly, such as the BOSE system in the HGU-56/P instead of an additional item to be maintained, taught, installed, and stocked. 60% of the original pilots have gone and new pilots do not have CEPs I like it. It works well. | 7 |
| | æ | I would like a more durable and sturdy product. I am always afraid of breaking them. | 9 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 9 | ĸ | Great system. Just make wiring system more durable (most pilots wash their earplugs with flight suit). | 7 |
| | 9 | Very, very fragile. | ٠ |
| | | They are great but break easily. | 7 |
| | ∞ | Greatly improves volume levels in the OH-58D, sometimes the FM radios are impossible to hear without CEP. | ٧ |
| | 6 | Great idea but poor design in durability. | 7 |
| | 10 | Very little. I don't like it. | - |
| 7. | | | 7 |
| | 2 | I think it's a great product or piece of equipment that is very much needed for the OH-58D(I) | 7 |
| | en | Although there are some minor problems with the CEP, it has significantly enhanced my ability to communicate within the cockpit and over the radios. I have absolutely no desire to give up my CEP and go back to my old helmet system | 7 |

| Q1 Unit location | Q1 ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 7. | 4 | It would have been nice to have an ICS setup so one would not need a CEP. I still have a difficult time understanding what is said because of the static. | ٠, |
| | s. | | , |
| | 9 | I do not want to fly without my CEP. Since wearing the CEP I can now hear everything in the cockpit. My overall rating for the CEP is excellent. | |
| | 7 | | vo |
| | ∞ | Very good device. | 7 |
| | 6 | I like them | , |
| | 10 | | 7 |
| | 11 | Outstanding, even with the minor problems. | , |
| | 12 | Great addition to aviation flight aids even with the minor problems. We need this device. | 7 |

| Q1 Unit location | QI Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 7. | 13 | I refuse to fly without them. It makes the job much easier. It's really obvious when flying with a pilot w/o the CEPs. I'll understand a radio message while the other pilot is saying "say again". | 7 |
| | 4 | It is a great idea! I use the CEP always. If the speaker was smaller and the wire stronger it would be a better product. Also the foam plug portion would be better if it held its form when compressed like yellow foam plugs do. | ٢ |
| | 15 | Great system, however the wire keeps breaking from the ear plug. | ٢ |
| | 16 | Drastic improvement over using foam ear plugs. Clear communications. You don't have to turn radios up full blast. The word is a hassle and time consuming but I still wouldn't be caught without my earplugs. Suggestion: make two connectors, one in each earcup. This will eliminate the cord catching on seatbelt and goggles. | 7 |
| | 11 | | 4 |
| | 81 | | ĸ |
| | 19 | Great idea - Needs a better design. We already have up to 3 wires hanging off our helmets. Adding another wire with the CEP does not help things. | 9 |
| | 20 | I like them! Make the plastic tube a bit shorter and more flexible. | 7 |
| | 21 | Really improves the ability to keep out outside noise from the aircraft. | |

| Q1 Unit location | QI Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 7. | 22 | They make hearing great. So much better than flying with earplugs but they are a hassle to put on. I only used them on real mission and just tolerated the lack of being able to hear the rest of the time. Bell needs to fix the aircraft so we can hear. CEPs need to be more comfortable like the ones the NASCAR drivers use. | S |
| | 23 | These have completely revolutionized aviation. It is terrific. The ability to hear everything is a critical part of aero-scouting and this has enhanced it greatly. I love them and I pity anyone without them. | 7 |
| œ | - | Alignment of goggles, they don't always align with my eyes, if we could get dual adjusting goggles - this would solve that | 7 |
| | 7 | I like the system, but the problem I have found is if I use plain foam earplugs, I cannot hear the ICS as well. If I wear the CEP everything sounds fine. Another concern of mine is that I hear a lot more acft noise wearing the HGU-56 and CEP system. | vo |
| | ю | Improves the internal and external communications. Allows me to monitor not only the radios but also copilot/student communication. | vo |
| | 4. | Good idea, ergonomically not the best product. | 9 |
| | 'n | Great system. | 9 |
| | 9 | Do not use. | |

| Q1 Unit location | QI Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| % | 7 | | - |
| | ∞ | I like them. They improve hearing significantly! | 7 |
| | 6 | Great device. You may not have it back. | 8 |
| | 10 | Worthwhile. | 9 |
| | = | Concerned about lack of maintenance or replacement. I will be seriously disappointed when my CEPs are no longer serviceable and there will be no replacement. | |
| | 12 | Good compromise/ low cost alternative to actually fixing the OH-58D ICS system. | 7 |
| | 13 | I would like to see rubber styles. They would last longer and fit easier. I love the increased audio clarity of the CEP, and I feel it is a must in the OH058D. However, it breaks too easy and the foam sizes are too restrictive and wear out too fast. | 9 |
| | . 41 | Great addition especially in the OH-58D (I) Kiowa Warrior. | 7 |
| | 15 | I have had experience flying/testing with an Active Noise Reduction system. I prefer that system because it removed or reduced unwanted noise. | ю |

| Q1 Unit location | QI ID Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| ∞ | 16 | Aviation is a noisy environment so most people wear earplugs on the flightline during pre-flight, etc. and this requires removing one set of plugs and replacing them with others. I like being able to hear, but the donning/doffing procedure stinks. It pulls out a lot which I can't stand. After a while you rig it so this doesn't occur. A lot of people do not use it for this reason. | \$ |
| | 17 | But in the end when all on correctly - hearing is great!! It does reduce noise level but it is more of a pain to maintain and use in a time critical environment. | т |
| 6 | - | | vo |
| · | 2 | This is the absolute best thing that R&D has added to the aircraft-Pilot interface I have seen. I can hear everything I need to without sacrificing my inner ear. The safety margin has been greatly increased now that ICS is clear and concise. Radio traffic is easily monitored. It is worth the slight amount of discomfort. I would personally buy my own set if not issued. | 7 |
| | m | Overall much better. | 7 |
| | 4 | Best thing to come along for 58D's, increases ability to hear everything. | 7 |
| | vs. | The speaker assembly should be smaller so it doesn't rub on the ear cup foam. The size of it causes extra pressure on ear canals. Suggest a molded type ear plug such as those used with race car helmets. | 7 |
| | 9 | I like the system despite the added steps. I can now actually turn down the volume on the ICS control. | 9 |

| Q1 Unit location | QI Num | Q44 General comments about CEP | Q45 Rate overall value of CEP |
|---------------------|-----------|----------------------------------------------------------------------------------------|-------------------------------|
| 6 | 7 | | 9 |
| | ∞ | Improvement. | 7 |
| | 6 | | vo |
| | 10 | | 8 |
| | == | | . % |
| | 13 | Why didn't somebody think of this before? | 7 |
| | 13 | Infinitely better. | 7 |
| | 14 | | |
| | 15 | Generally do not like HGU-56. Poorly engineered. Should not have to have modification. | |
| | 16 | | ţ |

| Q45 Rate overall value of CEP | 7 | Mean = 6.3 SD = 1.3 NR = 5 |
|-------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| Q44 General comments about CEP | Love them! Keep improving them and get them in the supply system immediately. One just must figure out which order to put on the equipment, goggles, CEP, helmet | |
| Q1 ID Num | 1 | N = 152 |
| Q1 Unit location | 10. | Overall total |

Reference

Murphy, B.A., and Mozo, B.T. 1999. <u>Flight Evaluation of the Communications Earplug</u> (CEP) in the OH-58D Helicopter. (Part 1) Fort Rucker, AL: U.S. Army Aeromedical Research Laboratory. USAARL Report No. 2000-04

Appendix.

EVALUATION OF THE COMMUNICATIONS EARPLUG IN THE OH-58D HELICOPTER ENVIRONMENT

INSTRUCTIONS: You have been asked to wear the Communications Earplug (CEP) in conjunction with your aviator helmet during your daily mission to evaluate its operational effectiveness and comfort. Please complete the following questionnaire. Most questions are self-explanatory with room for comment. Please try to be as precise as possible when making your comments. Some questions will require you to mark on a continuum between extremes. Your responses should be indicative of the strength of your feelings. Note: Please bear in mind that all comparison questions are between the helmet you normally used in the past and the CEP.

| Personal data: | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|
| 1. Unit location: | |
| 2. Today's date: | |
| 3. Sex:MF | |
| 4. Experience as an aviator: years. Approx. No. flight hours: | |
| 5. No. flight hours wearing HGU-56/P helmet (prior to CEP installation): | |
| 6. No. flight hours wearing CEP: Is the CEP still functioning properly?Yes No If no, describe the malfunction | |
| 7. CEP foam tip size: StandardSlimShortCombination | |
| 8. Seat position during most flights: | |
| 9. Do you have a waiver or information only letter (IO) for a hearing loss? YesNoNot Sure If Yes, how long have you been on waiver? | |
| 10. Do you normally wear eyeglasses when flying?YesNo If Yes, what type temples are on the glasses you normally wear?(examples: bayonet temples, wire frames of the property of the prop | etc) |
| Personal Hearing Protection: | |
| Prior to CEP installation, did you wear earplugs in conjunction with your flight helmet? YesNo If No, skip next question. | |
| 12. Did you frequently experience discomfort with your earplugs?YesNo If Yes, how long does it take before you feel the discomfort Describe the discomfort (example: itchiness, pain etc) | |
| 13. Prior to CEP installation, did you frequently experience discomfort with your helmet while flying? Yes No If Yes, how long does it take before you feel the discomfort? | |
| Describe the discomfort (examples: hot spots, headache etc) | |

| 14.4 | ttime. | ١ |
|------|--------|---|
| | Lung | |
| | | |

| 14. Have you experienced any difficulty in fitting the CEP?YesNo If Yes, please explain |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| |
| 15. Was there any discomfort when inserting the earplug?YesNo |
| 16. Do the wires pull on the CEP when turning your head?YesNo If Yes, please explain |
| 17. Does the CEP move or slip out of the ear during flight?YesNo If Yes, please explain |
| 18. Wire lengths of the CEP: SHORT wire wastoo short too longjust right. LONG wire wastoo short too longjust right. |
| 19. Were there any problems associated with CEP during night flights?YesNo |
| 20. Does the CEP catch on other equipment or interfere with job performance?YesNo If Yes, please explain |
| 21. Is the orientation or location of the connector convenient?YesNo If No, where would be your preference on the helmet |
| 22. After how many flight hours did you clean or change foam tips? |
| 23. How did you clean foam tips? |
| 24. Was there a problem of wax build-up in the CEP foam tip?YesNo |
| Comfort: |
| 25. Does the CEP cause any discomfort in your ear canals (itching, pain etc)?YesNo If Yes, was it :: :: Mildly Moderately Extremely uncomfortable uncomfortable uncomfortable |
| 26. Does the CEP cause any discomfort to your external ear?YesNo If Yes, please describe |
| 27. Are there any hot spots associated with CEP?YesNo If Yes, please explain |

| 20. | Please circle | the appropriate tin | | g your ingni | , when | ala you nrsi | nouce the di | scomfort? |
|-----|-------------------------------------------------------|---------------------------------------|--------------------|---------------|---------|-------------------------|---------------------|------------------------|
| | 1/2 hr | 1 hr 1-1/2 hrs | s 2 hrs | 2-1/2 hrs | 3 hrs | 3-1/2 hrs | 4 hrs | |
| 29. | With respect to ov | erall fit and comfo | ort, compar | e the CEP d | evice w | rith your per | sonal helmet. | |
| | Significantly Better | Moderately Better | Slightly Better | Same | : ; | Slightly Worse | Moderately Worse | Significantly Worse |
| Doi | nning and Doffing | : | | | | | | |
| 30. | Does the additionYesNo | of the CEP result If Yes, please e | | | | nning proce | | |
| 31. | Does this extra ste | p pose a significate explain | nt problem | in completin | ng your | mission? _ | _YesNo | |
| 32. | Do you have prob If Yes, please | | • | P with glove | | | .No | |
| 33. | If you forgot to di when the CEI If Yes, please | was removed? | Yes | | | | | |
| 34. | With respect to do | nning/doffing, cor | npare the te | est device to | your p | ersonal heln | net. | |
| | Significantly Better | Moderately Better | Slightly Better | Same | • | Slightly Worse | Moderately Worse | Significantly Worse |
| 35. | Rate the difference helmet. | e in <u>ICS</u> speech cla | arity/unders | standing who | en comp | pared to you | ır personal | |
| | Significantly Better | Moderately Better | Slightly Better | Same | ****** | Slightly Worse | Moderately Worse | Significantly Worse |
| 36. | Rate the difference to your person | | | - | | sed on gend | er of the talke | er when compared |
| | | _· <u></u> :_ | | Male Voice | : : | : | : | |
| | Significantly Better | Moderately Better | Slightly Better | Same | | Slightly Worse | Moderately Worse | Significantly Worse |
| | | | I | Female Voic | e . | | | |
| | Significantly Better | Moderately Better | Slightly Better | Same | | :_ Slightly Worse | Moderately Worse | Significantly Worse |

| 37. | Rate the helr | | in <u>overall</u> speech | n clarity/under | standing who | en compared | to your persona | 1 |
|-----|---------------|------------------------------|------------------------------------|--------------------|----------------|--------------------|---------------------|------------------------|
| | Sign Bet | nificantly ter | Moderately Better | Slightly Better | Same | Slightly Worse | Moderately Worse | Significantl Worse |
| Noi | ise Reduc | ction/Atten | uation: | | | | | |
| 38. | With res | pect to redu | icing noise level | s at your ears, | compare the | CEP to your | personal helme | t. |
| | Sigr Bet | nificantly ter | Moderately Better | Slightly Better | Same | :Slightly Worse | Moderately Worse | Significantly Worse |
| 39. | | | wing you to hear rsonal helmet. | navigational . | and caution/v | warning signal | ls, compare the | • |
| | Sign Bett | nificantly ter | Moderately Better | Slightly Better | Same | Slightly Worse | Moderately Worse | Significantly Worse |
| 40. | | pect to your | ability to hear a helmet. | and monitor no | oise generated | d by the aircra | off, compare the | CEP |
| | Sign Bett | ificantly er | Moderately Better | Slightly Better | Same | Slightly Worse | Moderately Worse | Significantly Worse |
| 41. | | pect to redu our personal | icing noise level helmet. | s at your ears | during weapo | ons firing, con | mpare the CEP | , |
| | Sign Bett | ificantly er | Moderately Better | Slightly Better | Same | Slightly Worse | Moderately Worse | Significantly Worse |
| Gen | eral Issu | es: | | | | | | |
| 42. | | re any adve es, please | rse effects of CE | P performanc | e?Yes | No | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| 13. | Please ela | borate on a | ny problems you | may have en | countered wh | nile wearing th | he CEP. | |
| | | | | | | | | |
| | | | | | | | | |

| 44. | General comments | about your exp | erience with | the CEP. | | | |
|--------------|--------------------------------------|----------------|---------------|-----------------|--------------|----------------|---------------|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 45.] | Based on your flyi personal helme | | ate the overa | ll value of the | CEP when con | mpared to your | |
| | | · | | : | : | ::_ | |
| 2 | Significantly | Moderately | Slightly | Same | Slightly | Moderately | Significantly |
| | Better | Better | Better | | Worse | Worse | Worse |